Supplement

Title: 113 Instruction Sheet Part Number: 3083192 Print Date: December 2007 Revision/Date: 1, 12/08 Supplement Issue:1Issue Date:11/10Page Count:1

This supplement contains information necessary to ensure the accuracy of the above Instruction Sheet.



© 2010 Fluke Corporation. All rights reserved.



113 Instruction Sheet

Supplement

Change #1

Under Replacement Parts:

Change: Fluke TL-75 (Double-insulated leads) 855705

To: Fluke TL175

3504931