

# Manual Supplement

Manual Title:	1750 Calibration	Supplement Issue:	1
Print Date:	November 2007	Issue Date:	6/10
Revision/Date:	1, 12/08	Page Count:	1

This supplement contains information necessary to ensure the accuracy of the above manual.



**205 Westwood Ave  
Long Branch, NJ 07740  
1-877-742-TEST (8378)  
Fax: (732) 222-7088  
salesteam@Tequipment.NET**

## Change #1

On page 10, under *Rogowski Current Verification*,

Change: 6. Press the **WAVE MENU** softkey and ensure the phase angle is  $-90^\circ$ .

To: 6. Press the **WAVE MENU** softkey and ensure the aux $\phi$ NRM phase angle is  $-90^\circ$ .

On page 11, under *CT Current Verification*,

Change: 5. Press the **WAVE MENU** softkey and ensure the phase angle is  $0.0^\circ$ .

To: 5. Press the **WAVE MENU** softkey and ensure the aux $\phi$ NRM phase angle is  $0.0^\circ$ .

