

# Supplement

Title: 3000A/6000A Flex 4 Instruction Sheet

Part Number: 3373047      Supplement Issue: 1

Print Date: Nov. 2008      Issue Date: 4/09

Revision/Date:      Page Count: 1

---

---

This supplement contains information necessary to ensure the accuracy of the above Instruction Sheet.



**205 Westwood Ave  
Long Branch, NJ 07740  
1-877-742-TEST (8378)  
Fax: (732) 222-7088  
[salesteam@Tequipment.NET](mailto:salesteam@Tequipment.NET)**

## Change #1

Under ***Operating Instructions***, add the following Note under step 3:

### *Note*

*The 1735 requires at least firmware version V1.07 and Power Log V2.8 or higher; older versions will give incorrect current readings. The latest versions of firmware for the 1735 may be downloaded from the Software Downloads page of the support area of the Fluke website.*

Before the ***Cleaning*** section, add the following:

## ***Software Updates***

The 174x Series requires at least PQLog V2.1.1 or higher. The latest version of software may be downloaded from the Software Downloads page of the support area of the Fluke website.