

Take this quiz and find out if you need I.S. tools on your job.

- 1) Do you work in any of these industries?
 - a. Petro-chemical
 - b. Oil platforms and refineries
 - c. Mining
 - d. Pharmaceutical
 - e. Pipelines (Natural gas, oil, etc.)
 - f. Power generation
 - g. Grain handling
- 2) Do you work where explosive gases may be present?
 - a. Yes
 - b. No
- 3) Do you work in the transport or work in an environment with any of these substances?
 - a. Acetylene
 - b. Ethylene
 - c. Gasoline
- d. Benzol
- e. Natural gas
- f. Heating oil/diesel
- g. Methane
- h. Propane
- i. Carbon disulphide
- j. Hydrogen

If you answered yes to any of these questions, please review the products in this brochure and the specific zones, types of protection, gas groups and temperature classes each instrument is approved for.

FLUKE ®

Making sense of the product rating systems

Each approved intrinsically safe device is rated to ATEX and either NEC or Factory Mutual (FM) Standards. The corresponding rating system allows you to understand which zones, type of protection, gas groups and temperature classes the instrument is approved for.

ATEX Example

Fluke 707Ex is XATEX Compliant II 2 G EEx ia IIC T4

The ATEX examination mark is required on all devices for use in European hazardous areas.

ATEX Markings

II 2 G The classification of zones. "II" designates the tool is approved for all non-mining areas. "2" represents the category of the device, in this case the device is rated for the second most hazardous areas. "G" designates atmosphere, in this case gas, vapors and mist.

EEx Explosion protection based on European Ex-regulations.

The type of protection from explosion, in this case the energy in a device or connector has been reduced to a safe value.

Gas Group. "IIC" rating indicates compatibility with the most dangerous gas groups.

Temperature class is the maximum temperature of a surface that may be.

FM Example

Fluke 707Ex is APPROVED FM-classified N.I. Class I, Div 2, Groups A-

The Factory Mutual Approved mark.

Factory Mutual Markings

Non-incendive apparatus, internal energy is limited so a specified atmosphere cannot be ignited by its use.

Class I For use with gases, vapors and liquids (not dust, fibers or filings).

Div 2 Certified for use in Zone 2, explosive atmospheres not normally present, may rarely exist for short duration.

Groups Rated for use with explosive gasses as defined by groups A-D, including acetylene, hydrogen, acetylene and propane.

> Fluke. Keeping your world up and running.

Fluke Corporation

PO Box 9090, Everett, WA USA 98206

Fluke Europe B.V. PO Box 1186, 5602 BD Eindhoven. The Netherlands For more information call:

In the USA (800) 443-5853 or Fax (425) 446-5116 In Europe/M-East/Africa (31 40) 2 675 200 or Fax (31 40) 2 675 222 In Canada (800) 36-FLUKE or Fax (905) 890-6866 From other countries +1 (425) 446-5500 or Fax +1 (425) 446-5116 Web access: http://www.fluke.com

©2005 Fluke Corporation. All rights reserved. Printed in U.S.A. 9/2005 2432675 B-EN-N Rev B



205 Westwood Ave Long Branch, NJ 07740 1-877-742-TEST (8378) Fax: (732) 222-7088 salesteam@Tequipment.NET

Fluke tools designed to keep you safe in dangerous environments



You need to meet tough maintenance and calibration tasks in potentially explosive and hazardous areas. That means you need reliable, accurate and intrinsically safe tools.

The complete line of Fluke tools includes the **NEW** 87V Ex **True-RMS Multimeter** and the **NEW** Fluke 68IS Infrared Thermometer to compliment the line of Fluke intrinsically safe field calibrators.

Read on to find out more about why intrinsic safety is important, how Fluke **Intrinsically Safe tools** can be used in your work and whether you need intrinsically safe tools in your job.



100.12

Fluke 725Ex

Multifunction

Process Calibrator





Fluke 718Ex **Pressure Calibrator Pressure Modules**



Fluke 87Ex **True-RMS Industrial** Multimeter



Fluke 700PEx

FLUKE

Infrared Thermometer



Fluke Intrinsically Safe products to help keep your employees safe

"Intrinsically Safe" or I.S. is a protection method employed in potentially explosive atmospheres. Certified I.S. tools are designed to prevent the release of sufficient energy to cause ignition of flammable material. I.S. standards apply to all equipment that can create one or more of a range of defined potential explosion sources:

- Electrical sparks
- Electrical arcs
- Flames
- Hot surfaces
- Static electricity
- Electromagnetic radiation
- Chemical reactions
- Mechanical impact
- Mechanical friction
- Compression ignition
- Acoustic energy
- Ionizing radiation

Industries that use or should use I.S. tools include:

- Petro-chemical
- Oil platforms and refineries
- Pharmaceutical
- Pipelines
- Anv environment where explosive gases or vapors could be present

Fluke 725Ex Multifunction Process Calibrator

Best suited for:



• Calibrating virtually any process parameter

- Features:
- Class I Div 1 Groups B-D 171 °C
- ATEX II IG EEx ia IIB 171 °C Compliant
- Measure, source or simulate volts dc, mA, RTDs, thermocouples frequency and ohms
- 2-channel simultaneous source and measure capability for calibration of transmitters
- Internal loop supply to power transmitters
- Store frequently-used test setups for later use
- Pressure measurement to 200 bar and pressure switch test using any of the 8 Fluke 700PEx pressure modules

Fluke 700PEx Pressure Modules

Best suited for:



 Use with the Fluke 725Ex Multifunctional Process Calibrator and Fluke 718Ex Pressure Calibrator to cover the most commonly used pressure calibration ranges from 0-25 mbar and 0-200 bar

- I.S. Class I Div 1 Groups A-D T4, $Ta = 0 \, ^{\circ}C \text{ to } +50 \, ^{\circ}C$
- ATEX II 1G EEx ia IIC T4 compliant
- Very high accuracy up to 0.025 %

Fluke 707Ex Loop Calibrator

• F.M. Class I Div 2 Groups A-D T4

easy interpretation of readings

• ATEX II 2G EEx ia IIC T4 compliant

Calibration and maintenance of 4 to 20 mA control loop

Pushbutton with 25 % steps for fast, easy linearity checks

• 0 and 100 % 'span check' for fast confirmation of zero and span

 Large display and simple, guick-click push/rotary button for easy one-handed operation

Simultaneous mA and % readout for quick,


Best suited for:

Fluke 68 Intrinsically Safe Infrared Thermometer

Best suited for:







- Enhanced optics (distance to spot ratio up to 50:1) allow the user to measure smaller objects from farther away
- Factory Mutual (a U.S. organization) approved as an Intrinsically Safe device (Class I, Division 1)
 (Customers outside of the United States should check with their national and company) regulations to see if which approvals are acceptable for their application.)
- Comfortable pistol grip make target pointing and easy job
- Backlit display for poorly lit areas
- Displays Min/Max measurements and saves readings in memory
- · Adjustable emissivity setting for more accurate measurements
- Log up to 12 measurements
- RTD contact probe

Best suited for:



• Pressure measurements and calibration in pressure ranges up to 200 bar


- Class I Div 1 Groups A-D T4 Compliant
- ATEX II IG EEx ia IIC T4 compliant
- Built-in pressure/vacuum hand pump, with vernier and
- Pressure measurement to 200 bar using any of the 8 Fluke 700PEx Pressure Modules
- Pressure measurement to 0.05 % of full span using internal pressure sensor
- Pressure switch test function

Fluke 87VEx Industrial Best suited for:

♦ ★

• Solving problems on motor drives, in plant automation, power distribution and electromechanical equipment

- Measure accurate voltage and frequency measurements on adjustable speed motor drives and other electrically noisy equip-
- Built-in thermometer allows you to take temperature readings
- Optional magnetic hanger for easy set-up and viewing while freeing your hands for
- Large digit display with bright, two-level





Motor Control Center


Flow Computer

Process Controller

Tank Farm

A Process Measurements

* Pumping Station





7, 180