



## PRODUCT BULLETIN

Bulletin No: PB178

Issue Date: October 3, 2003

**Product:** Parallel Remover (handle only)

*Part No:* FM2022-02



Specification:

Operating specifications from PB156 are unchanged.

## Comments:

The FM2022-02 is a replacement handle only. See PB176 for the complete Parallel Remover conversion kit.

Accessories: None.

Available: October 1, 2003

> For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

American Hakko Products, Inc. 28920 N. Avenue Williams. Valencia, CA 91355 Tel: (661) 294-0090 Fax: (661) 294-0096 www.hakkousa.com AHP14 Rev 2000-01

From...