



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB284

Issue Date: 11-7-2008

Description:

New Factory Burn-in Process for Hakko HJ5000 Heat Gun

Applies To:

HJ5000; HJ5000/P; HJ5000-RC-B; HJ5000-RC-G;
HJ5000-RC-O; HJ5000-RC-R

Specification:

Unchanged

Comments:

During the manufacturing process, residues are left on the heating element assembly which can cause light smoke and/or odor for the first few minutes of operation of a new heat gun. Due to customer concerns over the visible smoke, all HJ5000 heat guns are now burned in at the factory to burn off the manufacturing residue on the heating element assembly.

Available:

From HJ5000 shipments September 22, 2008 forward

