

PRODUCT BULLETIN

00000

Bulletin No: PB178

Issue Date: October 3, 2003

Product:

Parallel Remover (handle only)

Part No: FM2022-02

Specification:

Operating specifications from PB156 are unchanged.

For pricing information, please contact your local American Hakko

representative or our customer service department at (661) 294-0090.

Comments:

The FM2022-02 is a replacement handle only. See PB176 for the complete Parallel Remover conversion kit.

Accessories:

None.

Available:

October 1, 2003

From...

American Hakko Products, Inc. 28920 N. Avenue Williams. Valencia, CA 91355 Tel: (661) 294-0090 Fax: (661) 294-0096 www.hakkousa.com AHP14 Rev 2000-01