
PWDX	Mating Dlug	Dorma Tita 2®		
Part Number	Mating Plug Perma-Tite 2®	Perma-Tite 2®	Plug Bushing Kit	
Part Number	Perma-Tite 2®	Series Plug		
1610-PWDX	1510-PW6P			
1612-PWDX	1512-PW6P			
1614-PWDX	1514-PW6P			
1616-PWDX	1516-PW6P			
1620-PWDX	1520-PW6P			
1622-PWDX	1522-PW6P			
1624-PWDX	1524-PW6P			



Wall/Post Mount Kit 6260WK	(NM) Non Meta	(NM) Non Metallic Bushing Kits		Mira Mach Crina	
Optional Wall Mount Kit	82034 - 3/4"	82010 - 1"	Wire Mesh Grips		
D 66 N			82005W = 1/2"		
			82034W = 3/4"		
			82010W = 1"		
			82005W-1		
			82034W-1		









	Boxes for PW	/DX - Punched - No Bushing Kit		
	Part Number	Description		
	6212FS	Box, Std Depth, PWDX, No bushing, 1/2" NPT		
	6234FS	Box, Std Depth, PWDX, No bushing, 3/4" NPT		
	6210FS	Box, Std Depth, PWDX, No bushing, 1" NPT		
	6212FD	Box, Deep, PWDX, No bushing, 1/2" NPT		
	6234FD	Box, Deep, PWDX, No bushing, 3/4" NPT		
	6210FD	Box, Deep, PWDX, No bushing, 1" NPT		
	6212FT	Box, OPEN, PWDX, No bushing, 1/2" NPT		
	6234FT	Box, OPEN, PWDX, No bushing, 3/4" NPT		
	6210FT	Box, OPEN, PWDX, No bushing, 1" NPT		
	6212FSF	Box, Std Depth, PWDX, No Bushing, Feed thru, 1/2" NPT		
	6234FSF	Box, Std Depth, PWDX, No Bushing, Feed thru, 3/4" NPT		
رنگا رنگا	6210FSF	Box, Std Depth, PWDX, No Bushing, Feed thru, 1" NPT		
	6212FDF	Box, Deep, PWDX, No Bushing, Feed thru, 1/2" NPT		
	6234FDF	Box, Deep, PWDX, No Bushing, Feed thru, 3/4" NPT		
	6210FDF	Box, Deep, PWDX, No Bushing, Feed thru, 1" NPT		
	6212FTF	Box, OPEN, PWDX, No Bushing, Feed thru, 1/2" NPT		
	6234FTF	Box, OPEN, PWDX, No Bushing, Feed thru, 3/4" NPT		
	6210FTF	Box, OPEN, PWDX, No Bushing, Feed thru, 1" NPT		
		-		
	6212NFS	PT Bushing Installed (N = Non Metallic W = Wire Mesh) Box, Std Depth, PWDX, NM Bushing, 1/2" NPT	-c (ŮL) us —	
	6212NFD	Box, Deep, PWDX, NM Bushing, 1/2" NPT	LISTED —	
	6212NFT	Box, OPEN, PWDX, NM Bushing, 1/2" NPT		
	6212NFSF	Box, Std Depth, PWDX, NM Bushing, Feed thru, 1/2" NPT		
	6212NFDF	Box, Deep, PWDX, NM Bushing, Feed thru, 1/2" NPT		
	6212NFTF	Box, OPEN, PWDX, NM Bushing, Feed thru, 1/2" NPT		
	6212WFS	Box, Std Depth, PWDX, WireMesh Bushing, 1/2" NPT		
	6212WFD	Box, Deep, PWDX, WireMesh Bushing, 1/2" NPT		
	6212WFT	Box, OPEN, PWDX, WireMesh Bushing, 1/2" NPT		
	6212WFSF	Box, Std Depth, PWDX, WireMesh Bushing, Feed thru, 1/2" NPT		
	6212WFDF	Box, Deep, PWDX, WireMesh Bushing, Feed thru, 1/2" NPT		
	6212WFTF	Box, OPEN, PWDX, WireMesh Bushing, Feed thru, 1/2" NPT		
	Boxes for PWDX - 3/4" NF	PT Bushing Installed (N = Non Metallic W = Wire Mesh)	_(ĥr)—	
	6234NFS	Box, Std Depth, PWDX, NM Bushing, 3/4" NPT	_	
	6234NFD	Box, Deep, PWDX, NM Bushing, 3/4" NPT	LISTED	
	6234NFT	Box, OPEN, PWDX, NM Bushing, 3/4" NPT		
	6234NFSF	Box, Std Depth, PWDX, NM Bushing, Feed thru, 3/4" NPT		
	6234NFDF	Box, Deep, PWDX, NM Bushing, Feed thru, 3/4" NPT		
	6234NFTF	Box, OPEN, PWDX, NM Bushing, Feed thru, 3/4" NPT		
	6234WFS	Box, Std Depth, PWDX, WireMesh Bushing, 3/4" NPT		
	6234WFD	Box, Deep, PWDX, WireMesh Bushing, 3/4" NPT		
	6234WFT	Box, OPEN, PWDX, WireMesh Bushing, 3/4" NPT		
	6234WFSF	Box, Std Depth, PWDX, WireMesh Bushing, Feed thru, 3/4" NF	DT	
	6234WFDF	Box, Deep, PWDX, WireMesh Bushing, Feed thru, 3/4" NPT	<u>'</u>	
	6234WFTF	Box, OPEN, PWDX, WireMesh Bushing, Feed thru, 3/4" NPT		
		Bushing Installed (N = Non Metallic W = Wire Mesh)	-(パ୮)	
	6210NFS	Box, Std Depth, PWDX, NM Bushing, 1" NPT	LISTED	
	6210NFD	Box, Deep, PWDX, NM Bushing, 1" NPT		
	6210NFT	Box, OPEN, PWDX, NM Bushing, 1" NPT		
	6210NFSF	Box, Std Depth, PWDX, NM Bushing, Feed thru, 1" NPT		
	6210NFDF	Box, Deep, PWDX, NM Bushing, Feed thru, 1" NPT		
	6210NFTF	Box, OPEN, PWDX, NM Bushing, Feed thru, 1" NPT		
	6210WFS	Box, Std Depth, PWDX, WireMesh Bushing, 1" NPT		
	6210WFD	Box, Deep, PWDX, WireMesh Bushing, 1" NPT		
	6210WFT	Box, OPEN, PWDX, WireMesh Bushing, 1" NPT		
	6210WFSF	Box, Std Depth, PWDX, WireMesh Bushing, Feed thru, 1" NPT		
	6210WFDF	Box, Deep, PWDX, WireMesh Bushing, Feed thru, 1" NPT		
	6210WFTF	Box, OPEN, PWDX, WireMesh Bushing, Feed thru, 1" NPT		







