

POWER SUPPLY PREPARATION

- 1) Cut connector off of supply power cord, if so equipped.
- 2) Strip insulation 3/16 inch from end of wires.

POWER SUPPLY STYLE
MAY VARY

TERMINATION STYLE
MAY VARY



On products with a DC only input,
Polarity is important. Wire with
dashed white line is positive.

For product with a 12 VDC/9 VAC Input,
either polarity may be used.

POWER SUPPLY PREPARATION						
REV. LEVEL	REF. ECO	REV. DATE	APPROVED	DESCRIPTION	PRODUCT:	PART#
					DRAWN BY:	43099
					RLK	DATE:
					APPROVED BY:	03/12/09
					DWG.#	DATE:
					C-1026A	REV. PAGE OF
						1 1