



50 ft LASER & TAPE MEASURE

LTM1 QUICK START GUIDE

1



Install included batteries properly

2




Press once to find target

Press again for measurement


For assistance, please call (844)841-9878 to speak with our tech support specialists

REFERENCE



50ft

Laser measures from back of unit



Tape Lock Release Button on bottom

WARNING DO NOT RETRACT TAPE AT HIGH SPEED

Detailed user instructions can be found at www.generaltools.com