



INSTRUCTIONS FOR MOUNTING JONARD TOOLS [WISPY™](#) TO THE JONARD TOOLS [TELESCOPING POLE](#)



1. Select the 8-32 to 1/4-20 adapter that is provided with the [WISPY™](#)
2. Screw the 8-32 end of the adapter into the hole on the top of the platform located on the [TELESCOPING POLE](#)



3. Screw the flexible gooseneck rod onto the 8-32 to 1/4-20 adapter
4. Screw the [WISPY™](#) onto the end of the gooseneck as shown above

