



## 3-Phase Measuring Adapter - UK for PROFiTEST® C-UK

3-349-165-03  
2/11.07



**Attention!**  
Removing the Test Plug from the Measuring Adapter  
Disconnect L1, L2 and L3 from the mains  
before removing the test plug from the 3-phase  
measuring adapter.  
The measuring adapter can only be separated  
from the test plug with an appropriate tool.

