


Recommended Indicators Accessories for Bore Gages

Note: Among indicators other than those recommended, the following types of indicator cannot be used.

- Indicators with a total length of F and G of less than 31.8 mm
- Indicators with a measuring range of more than 12.7 mm (ISO/JIS Type)/0.9 in (AMSE/ANSI Type)
- Dust-proof and water-proof indicators with a contact point and spindle covered with rubber

Please contact us if you have any questions about products.



- In addition to bore gages, we offer a wide range of Digimatic indicators and dial indicators.

Some of the products recommended for use with bore gages are shown below.

RECOMMENDED INDICATORS




2046AB
Graduation 0.01 mm,
Measuring range 10 mm
Refer to page F-28 for details.



2109AB-10
Graduation 0.001 mm,
Measuring range 1 mm
Refer to page F-30 for details.



2972AB
One revolution type,
Graduation 0.01 mm,
Measuring range 1 mm
Refer to page F-40 for details.



2900AB-10
One revolution type,
Graduation 0.001 mm,
Measuring range 0.08 mm
Refer to page F-36 for details.



543-310B-10
ABSOLUTE Digimatic Indicator
Resolution 0.001 mm
Refer to page F-12 for details.



DIAL PROTECTION COVER

- The cover protects the indicator from unexpected impact while handling the bore gage.
- It can offer protection to indicators that are fitted with a lug or flat back.
- It can also be used for **543-310B-10 ID-C112GXB2**, an ABS Digimatic indicator for bore gages.

Note: This protection cover is intended to be attached to a bore gage and cannot be used for a dial indicator or Digimatic indicator alone.



Dial protection cover set
Order No. **21DZA000**



Unit: mm