

Pneumatic hand test pumps // -0.95...60 bar

P40.2 // P60



P40.2 Basic



P60 Solid



Highlights – P40.2

- Testing, adjustment and calibration of all types of pressure gauges
- 3 in 1: vacuum, low pressure and medium pressure calibration
- Exact adjustment in the mbar range thanks to ultra-fine thread pitch and large volume control valve
- Tool-free change between positive pressure and vacuum generation

Highlights – P60

- Like P40.2
- Single pneumatic hand pressure pump up to 60 bar

Technical Data

Common data		
Type	P40.2	P60
Pressure ranges → Negative pressure → Positive pressure	-0.95 bar 40 bar	-0.95 bar 60 bar
Pressure medium	Air	
Connections		
Reference pressure gauge	G¼	
Test sample	G¼ with quick coupling and pressure hose (1 m)	
Basic		
Dimensions	Approx. 240 x 170 x 50 mm	
Weight	Approx. 1.1 kg	
Solid		
Dimensions (case)	Approx. 450 x 370 x 110 mm	
Weight	Approx. 4.2 kg	
+ Adapter kit	Chrome-plated brass, G⅛, G¼, G⅜, G½, ⅛ NPT, ¼ NPT, ½ NPT, M12 x 1.5, M20 x 1.5, G⅛, G¼	
+ Seal kit	PA flat gaskets and O-rings	

Article numbers

Order code		
Type	Version	Order number
P40.2	Basic	EPPM040EBL0000
	Solid (incl. case and adapter)	EPPM0400BL0000
P60	Basic	EPPM060EBL0000
	Solid (incl. case and adapter))	EPPM0600BL0000