



American Hakko Products, Inc.

# PRODUCT BULLETIN

**Bulletin No:** PB399

**Issue Date:** 10-25-2016

**Available:** 10-25-2016

**Product Description:**



HAKKO B5086 Lead Adjuster for FT-8002

**Part No:**

B3644 to B5086

**Specification:**

Unchanged



**Comments:**

The HAKKO B3644 lead adjuster for the FT-8002 handpiece will discontinue and the new B5086 will be a direct and improved replacement. The HAKKO B3644 has changed to increase the FT-8002 handpiece's operability. The new HAKKO B5086 will now mount from the opposite side of the handpiece and has changed shape to help prevent the adjuster plate from bending. The new HAKKO B5086 lead adjuster comes with FT801-02 and FT8002-CK or may be purchased individually.

All shipments of the HAKKO FT801-02 with serial number 11801216000725 or later will include the new B5086 lead adjuster. All shipments of the HAKKO FT8002-CK on or after November 10, 2016 will include the new B5086 lead adjuster.

For more information please visit us at [www.HakkoUSA.com](http://www.HakkoUSA.com)

AHP14 Rev 2012-11