

Packing List

The following items are included:



DT80

Hose Connector 1 unit

0034779-071024

JBC

www.jbctools.com

INSTRUCTION MANUAL




DT80

Hose Connector
for DT530

Cover Replacement

Hold down the tool with one hand onto the stand (1) and grasp the suction hose at the point where it meets the protective cover and pull upwards (2) to undock the solder-collector group from the heating element.


 Be careful when manipulating the tool. The metal and glass parts may be hot.



www.jbctools.com



Remove the suction hose from the nozzle of the hose connector. Remove the protective cover by pulling it out and then remove the hose connector as well and replace it with the new one. Reassemble the new hose connector to the solder collector, place back the protective cover onto the nozzle of the hose connector and connect again the suction hose.



Reassemble the whole solder-collector group onto the desoldering tool.