

HANSER




Table of Contents

Chris Rauwendaal

Polymer Extrusion

ISBN (Buch): 978-1-56990-516-6

For further information and order see

<http://www.hanser-fachbuch.de/978-1-56990-516-6>

or contact your bookseller.

Contents

Preface to the Fifth Edition	v
1 Introduction	1
1.1 Basic Process	1
1.2 Scope of the Book	2
1.3 General Literature Survey	3
1.4 History of Polymer Extrusion	6
Part I – Extrusion Machinery	11
2 Different Types of Extruders	13
2.1 The Single Screw Extruder	13
2.1.1 Basic Operation	15
2.1.2 Vented Extruders	16
2.1.3 Rubber Extruders	17
2.1.4 High-Speed Extrusion	22
2.1.4.1 Melt Temperature	22
2.1.4.2 Extruders without Gear Reducer	23
2.1.4.3 Energy Consumption	23
2.1.4.4 Change-over Resin Consumption	23
2.1.4.5 Change-over Time and Residence Time	24
2.2 The Multiscrew Extruder	24
2.2.1 The Twin Screw Extruder	24
2.2.2 The Multiscrew Extruder With More Than Two Screws	25
2.2.3 The Gear Pump Extruder	27
2.3 Disk Extruders	28
2.3.1 Viscous Drag Disk Extruders	28
2.3.1.1 Stepped Disk Extruder	28
2.3.1.2 Drum Extruder	30
2.3.1.3 Spiral Disk Extruder	31
2.3.1.4 Diskpack Extruder	31
2.3.2 The Elastic Melt Extruder	35
2.3.3 Overview of Disk Extruders	36
2.4 Ram Extruders	36
2.4.1 Single Ram Extruders	37
2.4.1.1 Solid State Extrusion	38
2.4.2 Multi Ram Extruder	41

2.4.3 Appendix 2.1	42
2.4.3.1 Pumping Efficiency in Diskpack Extruder	42
3 Extruder Hardware	49
3.1 Extruder Drive	49
3.1.1 AC Motor Drive System	49
3.1.1.1 Mechanical Adjustable Speed Drive	50
3.1.1.2 Electric Friction Clutch Drive	50
3.1.1.3 Adjustable Frequency Drive	51
3.1.2 DC Motor Drive System	53
3.1.2.1 Brushless DC Drives	55
3.1.3 Hydraulic Drive System	55
3.1.4 Comparison of Various Drive Systems	58
3.1.5 Reducer	59
3.1.6 Constant Torque Characteristics	60
3.2 Thrust Bearing Assembly	61
3.3 Barrel and Feed Throat	64
3.4 Feed Hopper	68
3.5 Extruder Screw	70
3.6 Die Assembly	72
3.6.1 Screens and Screen Changers	72
3.7 Heating and Cooling Systems	75
3.7.1 Electric Heating	75
3.7.1.1 Resistance Heating	75
3.7.1.2 Induction Heating	76
3.7.2 Fluid Heating	77
3.7.3 Extruder Cooling	77
3.7.4 Screw Heating and Cooling	80
4 Instrumentation and Control	85
4.1 Instrumentation Requirements	85
4.1.1 Most Important Parameters	86
4.2 Pressure Measurement	87
4.2.1 The Importance of Melt Pressure	87
4.2.2 Different Types of Pressure Transducers	88
4.2.3 Mechanical Considerations	92
4.2.4 Specifications	93
4.2.5 Comparisons of Different Transducers	96
4.3 Temperature Measurement	96
4.3.1 Methods of Temperature Measurement	97
4.3.2 Barrel Temperature Measurement	100
4.3.3 Stock Temperature Measurement	102
4.3.3.1 Ultrasound Transmission Time	105
4.3.3.2 Infrared Melt Temperature Measurement	106
4.4 Other Measurements	107
4.4.1 Power Measurement	107

4.4.2	Rotational Speed	109
4.4.3	Extrudate Thickness	110
4.4.4	Extrudate Surface Conditions	114
4.5	Temperature Control	116
4.5.1	On-Off Control	117
4.5.2	Proportional Control	119
4.5.2.1	Proportional-Only Control	119
4.5.2.2	Proportional and Integral Control	123
4.5.2.3	Proportional and Integral and Derivative Control	124
4.5.2.4	Dual Sensor Temperature Control	125
4.5.3	Controllers	126
4.5.3.1	Temperature Controllers	126
4.5.3.2	Power Controllers	126
4.5.3.3	Dual Output Controllers	128
4.5.4	Time-Temperature Characteristics	128
4.5.4.1	Thermal Characteristics of the System	128
4.5.4.2	Modeling of Response in Linear Systems	130
4.5.4.3	Temperature Characteristics with On-Off Control	133
4.5.5	Tuning of the Controller Parameters	135
4.5.5.1	Performance Criteria	135
4.5.5.2	Effect of PID Parameters	136
4.5.5.3	Tuning Procedure When Process Model Is Unknown	137
4.5.5.4	Tuning Procedure When Process Model Is Known	138
4.5.5.5	Pre-Tuned Temperature Controllers	139
4.5.5.6	Self-Tuning Temperature Controllers	140
4.6	Total Process Control	140
4.6.1	True Total Extrusion Process Control	141
Part II – Process Analysis		147
5	Fundamental Principles	149
5.1	Balance Equations	149
5.1.1	The Mass Balance Equation	149
5.1.2	The Momentum Balance Equation	150
5.1.3	The Energy Balance Equation	151
5.2	Basic Thermodynamics	153
5.2.1	Rubber Elasticity	157
5.2.2	Strain-Induced Crystallization	159
5.3	Heat Transfer	160
5.3.1	Conductive Heat Transfer	160
5.3.2	Convective Heat Transfer	161
5.3.3	Dimensionless Numbers	161
5.3.3.1	Dimensional Analysis	161
5.3.3.2	Important Dimensionless Numbers	163
5.3.4	Viscous Heat Generation	168
5.3.5	Radiative Heat Transport	169
5.3.5.1	Dielectric Heating	171
5.3.5.2	Microwave Heating	173

5.4	Basics of Devolatilization	175
5.4.1	Devolatilization of Particulate Polymer	180
5.4.2	Devolatilization of Polymer Melts	181
Appendix 5.1		185
	Example: Pipe Flow of Newtonian Fluid	185
6	Important Polymer Properties	191
6.1	Properties of Bulk Materials	191
6.1.1	Bulk Density	191
6.1.2	Coefficient of Friction	194
6.1.3	Particle Size and Shape	200
6.1.4	Other Properties	201
6.2	Melt Flow Properties	202
6.2.1	Basic Definitions	202
6.2.2	Power Law Fluid	208
6.2.3	Other Fluid Models	213
6.2.4	Effect of Temperature and Pressure	214
6.2.5	Viscoelastic Behavior	218
6.2.6	Measurement of Flow Properties	220
6.2.6.1	Capillary Rheometer	220
6.2.6.2	Melt Index Tester	223
6.2.6.3	Cone and Plate Rheometer	227
6.2.6.4	Slit Die Rheometer	228
6.2.6.5	Dynamic Analysis	230
6.3	Thermal Properties	233
6.3.1	Thermal Conductivity	234
6.3.2	Specific Volume and Morphology	236
6.3.3	Specific Heat and Heat of Fusion	239
6.3.4	Specific Enthalpy	241
6.3.5	Thermal Diffusivity	242
6.3.6	Melting Point	245
6.3.7	Induction Time	245
6.3.8	Thermal Characterization	247
6.3.8.1	DTA and DSC	247
6.3.8.2	TGA	247
6.3.8.3	TMA	248
6.3.8.4	Other Thermal Characterization Techniques	248
6.4	Polymer Property Summary	248
7	Functional Process Analysis	255
7.1	Basic Screw Geometry	255
7.2	Solids Conveying	258
7.2.1	Gravity Induced Solids Conveying	259
7.2.1.1	Pressure Distribution	262
7.2.1.2	Flow Rate	265
7.2.1.3	Design Criteria	266

7.2.2	Drag Induced Solids Conveying	268
7.2.2.1	Frictional Heat Generation	282
7.2.2.2	Grooved Barrel Sections	284
7.2.2.3	Adjustable Grooved Barrel Extruders	296
7.2.2.4	Starve Feeding Versus Flood Feeding	302
7.3	Plasticating	305
7.3.1	Theoretical Model of Contiguous Solids Melting	306
7.3.1.1	Non-Newtonian, Non-Isothermal Case	316
7.3.2	Other Melting Models	326
7.3.3	Power Consumption in the Melting Zone	330
7.3.4	Computer Simulation	332
7.3.5	Dispersed Solids Melting	333
7.4	Melt Conveying	340
7.4.1	Newtonian Fluids	343
7.4.1.1	Effect of Flight Flanks	348
7.4.1.2	Effect of Clearance	350
7.4.1.3	Power Consumption in Melt Conveying	353
7.4.2	Power Law Fluids	356
7.4.2.1	One-Dimensional Flow	356
7.4.2.2	Two-Dimensional Flow	361
7.4.3	Non-Isothermal Analysis	367
7.4.3.1	Newtonian Fluids with Negligible Viscous Dissipation	367
7.4.3.2	Non-Isothermal Analysis of Power Law Fluids	374
7.4.3.3	Developing Temperatures	387
7.4.3.4	Estimating Fully Developed Melt Temperatures	404
7.4.3.5	Assumption of Stationary Screw and Rotating Barrel	411
7.5	Die Forming	419
7.5.1	Velocity and Temperature Profiles	420
7.5.2	Extrudate Swell	429
7.5.3	Die Flow Instabilities	431
7.5.3.1	Shark Skin	431
7.5.3.2	Melt Fracture	432
7.5.3.3	Draw Resonance	434
7.6	Devolatilization	435
7.7	Mixing	441
7.7.1	Mixing in Screw Extruders	442
7.7.1.1	Distributive Mixing in Screw Extruders	447
7.7.2	Static Mixing Devices	457
7.7.2.1	Geometry of Static Mixers	460
7.7.2.2	Functional Performance Characteristics	464
7.7.2.3	Miscellaneous Considerations	468
7.7.3	Dispersive Mixing	469
7.7.3.1	Solid-Liquid Systems	469
7.7.3.2	Liquid-Liquid System	471
7.7.4	Backmixing	483
7.7.4.1	Cross-Sectional Mixing and Axial Mixing	483

7.7.4.2 Residence Time Distribution	485
7.7.4.3 RTD in Screw Extruders	487
7.7.4.4 Methods to Improve Backmixing	488
7.7.4.5 Conclusions for Backmixing	490
Appendix 7.1	491
Appendix 7.2	492
Appendix 7.3	493
8 Extruder Screw Design	509
8.1 Mechanical Considerations	510
8.1.1 Torsional Strength of the Screw Root	510
8.1.2 Strength of the Screw Flight	512
8.1.3 Lateral Deflection of the Screw	514
8.2 Optimizing for Output	519
8.2.1 Optimizing for Melt Conveying	519
8.2.2 Optimizing for Plasticating	530
8.2.2.1 Effect of Helix Angle	532
8.2.2.2 Effect of Multiple Flights	532
8.2.2.3 Effect of Flight Clearance	534
8.2.2.4 Effect of Compression Ratio	536
8.2.3 Optimizing for Solids Conveying	537
8.2.3.1 Effect of Channel Depth	537
8.2.3.2 Effect of Helix Angle	538
8.2.3.3 Effect of Number of Flights	539
8.2.3.4 Effect of Flight Clearance	539
8.2.3.5 Effect of Flight Geometry	539
8.3 Optimizing for Power Consumption	540
8.3.1 Optimum Helix Angle	541
8.3.2 Effect of Flight Clearance	543
8.3.3 Effect of Flight Width	544
8.4 Single-Flighted Extruder Screws	548
8.4.1 The Standard Extruder Screw	549
8.4.2 Modifications of the Standard Extruder Screw	550
8.5 Devolatilizing Extruder Screws	553
8.5.1 Functional Design Considerations	554
8.5.2 Various Vented Extruder Screw Designs	558
8.5.2.1 Conventional Vented Extruder Screw	558
8.5.2.2 Bypass Vented Extruder Screw	559
8.5.2.3 Rearward Devolatilization	560
8.5.2.4 Multi-Vent Devolatilization	561
8.5.2.5 Cascade Devolatilization	562
8.5.2.6 Venting through the Screw	563
8.5.2.7 Venting through a Flighted Barrel	564
8.5.3 Vent Port Configuration	565
8.6 Multi-Flighted Extruder Screws	568
8.6.1 The Conventional Multi-Flighted Extruder Screw	568

8.6.2	Barrier Flight Extruder Screws	569
8.6.2.1	The Maillerer Screw	572
8.6.2.2	The Barr Screw	575
8.6.2.3	The Dray and Lawrence Screw	578
8.6.2.4	The Kim Screw	579
8.6.2.5	The Ingen Housz Screw	580
8.6.2.6	The CRD Barrier Screw	581
8.6.2.7	Summary of Barrier Screws	582
8.7	Mixing Screws	584
8.7.1	Dispersive Mixing Elements	584
8.7.1.1	The CRD Mixer	602
8.7.1.2	Mixers to Break Up the Solid Bed	616
8.7.1.3	Summary of Dispersive Mixers	618
8.7.2	Distributive Mixing Elements	619
8.7.2.1	Ring or Sleeve Mixers	621
8.7.2.2	Variable Depth Mixers	622
8.7.2.3	Summary of Distributive Mixers	623
8.8	Efficient Extrusion of Medical Devices	624
8.8.1	Introduction	624
8.8.2	Good Manufacturing Practices in Medical Extrusion	625
8.8.3	Automation of the Medical Extrusion Process	625
8.8.4	Minimizing Polymer Degradation	626
8.8.5	Melt Temperatures Inside the Extruder	626
8.8.6	Melt Temperatures and Screw Design	627
8.8.7	Molecular Degradation and Screw Design	630
8.8.8	Conclusions	634
8.9	Scale-Up	635
8.9.1	Common Scale-Up Factors	635
8.9.2	Scale-Up for Heat Transfer	638
8.9.3	Scale-Up for Mixing	639
8.9.4	Comparison of Various Scale-Up Methods	640
8.10	Rebuilding Worn Screws and Barrels	642
8.10.1	Application of Hardfacing Materials	644
8.10.1.1	Oxyacetylene Welding	644
8.10.1.2	Tungsten Inert Gas Welding	645
8.10.1.3	Plasma Transfer Arc Welding	645
8.10.1.4	Metal Inert Gas Welding	646
8.10.1.5	Laser Hardfacing	646
8.10.2	Rebuilding of Extruder Barrels	646
9	Die Design	653
9.1	Basic Considerations	654
9.1.1	Balancing the Die by Adjusting the Land Length	655
9.1.2	Balancing by Channel Height	659
9.1.3	Other Methods of Die Balancing	662

9.2	Film and Sheet Dies	663
9.2.1	Flow Adjustment in Sheet and Film Dies	664
9.2.2	The Horseshoe Die	667
9.3	Pipe and Tubing Dies	668
9.3.1	Tooling Design for Tubing	671
9.3.1.1	Definitions of Various Draw Ratios	672
9.3.1.2	Land Length	673
9.3.1.3	Taper Angles	674
9.3.1.4	Special Features	676
9.4	Blown Film Dies	676
9.4.1	The Spiral Mandrel Geometry	679
9.4.2	Effect of Die Geometry on Flow Distribution	680
9.4.3	Summary of Spiral Mandrel Die Design Variables	684
9.5	Profile Extrusion Dies	684
9.6	Coextrusion	686
9.6.1	Interface Distortion	690
9.7	Calibrators	692
10	Twin Screw Extruders	697
10.1	Introduction	697
10.2	Twin versus Single Screw Extruder	699
10.3	Intermeshing Co-Rotating Extruders	701
10.3.1	Closely Intermeshing Extruders	701
10.3.2	Self-Wiping Extruders	704
10.3.2.1	Geometry of Self-Wiping Extruders	705
10.3.2.2	Conveying in Self-Wiping Extruders	713
10.4	Intermeshing Counter-Rotating Extruders	720
10.5	Non-Intermeshing Twin Screw Extruders	730
10.6	Coaxial Twin Screw Extruders	743
10.7	Devolatilization in Twin Screw Extruders	745
10.8	Commercial Twin Screw Extruders	749
10.8.1	Screw Design Issues for Co-Rotating Twin Screw Extruders	753
10.8.2	Scale-Up in Co-Rotating Twin Screw Extruders	756
10.9	Overview of Twin Screw Extruders	758
11	Troubleshooting Extruders	763
11.1	Requirements for Efficient Troubleshooting	763
11.1.1	Instrumentation	764
11.1.2	Understanding of the Extrusion Process	764
11.1.3	Collect and Analyze Historical Data (Timeline)	765
11.1.4	Team Building	766
11.1.5	Condition of the Equipment	766
11.1.6	Information on the Feedstock	767
11.2	Tools for Troubleshooting	768
11.2.1	Temperature Measurement Devices	768

11.2.2	Data Acquisition Systems (DAS)	769
11.2.2.1	Portable Data Collectors/Machine Analyzers	769
11.2.2.2	Fixed Station Data Acquisition Systems	770
11.2.3	Light Microscopy	772
11.2.4	Thermochromic Materials	773
11.2.5	Thermal Analysis	775
11.2.6	Miscellaneous Tools	775
11.3	Systematic Troubleshooting	776
11.3.1	Upsets versus Development Problems	776
11.3.2	Machine-Related Problems	776
11.3.2.1	Drive System	776
11.3.2.2	The Feed System	778
11.3.2.3	Different Feeding Systems	778
11.3.2.4	Heating and Cooling System	778
11.3.2.5	Wear Problems	780
11.3.2.6	Screw Binding	797
11.3.3	Polymer Degradation	803
11.3.3.1	Types of Degradation	803
11.3.3.2	Degradation in Extrusion	807
11.3.4	Extrusion Instabilities	820
11.3.4.1	Frequency of Instability	821
11.3.4.2	Functional Instabilities	828
11.3.4.3	Solving Extrusion Instabilities	833
11.3.5	Air Entrapment	834
11.3.6	Gels, Gel Content, and Gelation	836
11.3.6.1	Measuring Gels	839
11.3.6.2	Gels Created in the Extrusion Process	840
11.3.6.3	Removing Gels Produced in Polymerization	841
11.3.7	Die Flow Problems	843
11.3.7.1	Melt Fracture	843
11.3.7.2	Die Lip Build-Up (Die Drool)	845
11.3.7.3	V- or W-Patterns	846
11.3.7.4	Specks and Discoloration	846
11.3.7.5	Lines in Extruded Product	851
11.3.7.6	Optical Properties	853
12	Modeling and Simulation of the Extrusion Process	861
12.1	Introduction	861
12.2	Background	862
12.2.1	Analytical Techniques	862
12.2.2	Numerical Methods	864
12.2.2.1	Finite Difference Method	865
12.2.2.2	Finite Element Method	866
12.2.2.3	Boundary Element Method	867
12.2.3	Remeshing Techniques in Moving Boundary Problems	868
12.2.4	Rheology	870

12.3 Simulating 3-D Flows with 2-D Models	871
12.3.1 Simulating Flows in Internal Batch Mixers with 2-D Models	871
12.3.2 Simulating Flows in Extrusion with 2-D Models	877
12.3.3 Simulating Flows in Extrusion Dies with 2-D Models	881
12.4 Three-Dimensional Simulation	885
12.4.1 Simulating Flows in the Banbury Mixer with Three-Dimensional Models	885
12.4.2 Simulating Flows in Extrusion Dies with 3-Dimensional Models	887
12.4.3 Simulating Flows in Extrusion with 3-Dimensional Models	892
12.4.3.1 Regular Conveying Screw	892
12.4.3.2 Energy Transfer Mixer	893
12.4.3.3 Twin Screw Extruder	895
12.4.3.4 Rhomboidal Mixers and Fluted Mixers (Leroy/Maddock)	901
12.4.3.5 Turbo-Screw	906
12.4.3.6 CRD Mixer	908
12.4.4 Static Mixers	910
12.5 Conclusions	912
Conversion Constants	919
Length	919
Volume	919
Mass	920
Density	920
Force	920
Stress	921
Viscosity	921
Energy/Work	922
Power	922
Specific Energy	922
Thermal Conductivity	923
Temperature	923
Index	925