



3933 US ROUTE 11, CORTLAND, NEW YORK 13045  
Phone Number: 1-800-345-3851 Fax Number: 607-758-3648

## REPORT OF TEST


RENDERED TO:  
Panduit Corporation  
10500 167th Street  
Orland Park, IL 60467

The products described in this Report were tested and examined by Intertek for compliance to the standards listed below. The products listed below are not part of an Intertek Verification Program. The results are provided to the client as a one time performance test and shall not be utilized to imply compliance to the standard as part of an on-going program.

Reference Intertek Report No.: 3183508CRT-006a

Date: July 14, 2009

4 Connectors channel:



<u>Component Id</u>	<u>Manufacturer</u>	<u>Description</u>	<u>Part number</u>
1	Panduit	Patch Cord	NK5EPC10Y
2	Panduit	Module	NK5E88M**Y
3	Panduit	Horizontal Cable	NUL5C04**-CE
4	Panduit	Transition Point	P110B100-X
5	Panduit	Patch Cord	NK5EPC14**Y


### Conclusion:

The channel configuration, as previously described, was tested in accordance with the following standard:

ISO/IEC 11801 Information Technology - Generic cabling for customer premises, Second edition dated September 2002 including Amendment 1, dated August 2008 (for Class D channel requirements)

The channel configuration was found to be in compliance with the applicable standard. The testing was performed at Intertek, located in Cortland, NY.

Reviewed and approved by:

  
John Cash  
Technician  
Global Cabling Products Testing

  
Antoine Pelletier  
Engineer  
Global Cabling Products Testing

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.