



# NEW PRODUCT!

Announcement Number: S04091904

## #4T65-AFL


### Actuator feed limit (AFL) valve repair

All 4T65 1997-on

Includes AFL valve, bushing, spring and spacer

### CORRECTS/PREVENTS/REDUCES:

Code P01811 Maximum adapt, wrong gear starts, ratio codes hot, TCC slip



New AFL Bushing & Valve

orange spring

Reuse retainer



## Drop-in fix for worn actuator feed limit bores. NO REAMING. NO SPECIAL TOOLING.

Discard the original AFL valve and spring, but keep the original retainer to reuse. Install the new bushing, valve, orange spring, spacer and original retainer.

Note: During installation of the new bushing, it might be tight due to the wear ridge. If necessary, use either end of the old valve to push the new bushing into place. Once installed, the bushing never moves in the bore, so it's alright if it's tight.

**That's it—It's fixed!**  
**Enjoy the rest of your day.**



**ENGINEERED FOR PERFORMANCE.**  
**DESIGNED FOR DURABILITY.**

©TransGo. All rights reserved. TransGo®, Shift Kit®, SK® and Reprogramming Kit™ are registered and licensed trademarks.



Tech Support 626.443.7451



techinfo@transgo.com