

HEAVY DUTY TOGGLES



Fig. 1



Fig. 2



Fig. 3



Fig. 4



Fig. 5



Fig. 6



Fig. 7



Fig. 8



Fig. 9



Fig. 10



Fig. 11



Fig. 12

Retail Part No.	Figure No.	Circuit Function			Poles/Throws	AMPS 125VAC	AMPS 250VAC	HP 125-250VAC	Actuator Style	Actuator Material	Bushing Length	Mounting Hole	Terminal Type	Hardware	Spec. Drawing Page No.
35-078	1	On		Off	SPST	15	10	3/4	Bat	Metal					H-13 A
35-143	2	On	Off	On	4PDT	15	10	3/4	Bat	Metal	0.465"	0.500"	Screw	N, FN, Sc	H-13 B
35-3080	2	On		On	4PDT	15	10	3/4	Bat	Metal	0.465"	0.500"	Screw	N, FN, Sc	H-13 B
35-3135	3	**	10n	Off	†	15	10	1/2	Bat	Brass	0.468"	0.500"	Screw	N, FN, Sc	H-13 C
35-126	4	On		Off	DPST	16	8	1	Bat	Metal	0.465"	0.500"	Screw	N, FN	H-13 D
35-3070	4	On		Off	SPST	16	8	1-1/2	Bat	Metal	0.465"	0.500"	Screw	N, Sc	H-13 E
35-140	5	On	Off	On	3PDT	17	12	1-1/2	Bat	Metal	0.465"	0.500"	Screw	N, FN, Sc	H-13 F
35-141	5	On		On	3PDT	17	12	1-1/2	Bat	Metal	0.465"	0.500"	Screw	N, FN, Sc	H-13 F
35-080	6	On		Off	SPST	20	10*	3/4	Bat	Metal	0.470"	0.500"	Screw	N, KN, Sc, ID	H-13 G
35-144	7	On		On	DPDT	20	10*	1-1/2	Bat	Metal	0.465"	0.500"	Solder	N, KN	H-13 I
35-146	6	On		On	DPDT	20	10*	1-1/2	Bat	Metal	0.470"	0.500"	Screw	N, KN, Sc	H-13 I
35-149	7	On	Off	On	DPDT	20	10	3/4	Bat	Metal	0.465"	0.500"	Solder	N, KN	H-13 I
35-150	6	(On)	Off	(On)	DPDT	20	10*	1-1/2	Bat	Metal	0.470"	0.500"	Screw	N, KN, Sc	H-13 I
35-151	6	On	Off	(On)	DPDT	20	10*	1-1/2	Bat	Metal	0.470"	0.500"	Screw	N, KN, Sc	H-13 I
35-153	8	On	Off	(On)	SPDT	20	10*	3/4	Bat	Metal	0.470"	0.500"	Screw	N, KN, Sc	H-13 H
35-3015	9	On	Off	On	SPDT	20	10	3/4	Bat	Brass	0.325"	0.500"	QC .250"	N, KN	H-13 J
35-3025	7	On	Off	On	DPDT	20	10*	1-1/2	Bat	Brass	0.468"	0.500"	QC .250"	N, KN	H-13 K
35-3045	10	On		Off	DPST	20	10	3/4	Bat	Brass	0.468"	0.500"	QC .250"	N, KN	H-13 L
35-3055	9	Off		(On)	SPST	20	10	3/4	Bat	Brass	0.468"	0.500"	QC .250"	N, KN	H-13 J
35-3056	9	On		Off	SPST	20	10	3/4	Bat	Brass	0.325"	0.500"	Solder	N,KN	H-13 J
35-3075	11	On		Off	DPST	20	10	1-1/2	Bat	Brass	0.465"	0.500"	Screw	N, Sc	H-13 E
35-3170	12	On		Off	SPST	***	***	1/2	Bat	Brass	0.500"	0.438"	Screw	KN, Sc	H-13 M

Notes: (On)/(Off) = Momentary On/Off

*Rated @ 277VAC

**1&2 On

***Rated 35A @ 6VDC/20A @ 12VDC

FN = Face Nut

† = Progressive Two Circuit

ID = ID Plate

KN = Knurled Nut

N = Nut

QC = Quick Connect

Sc = Screw

Note: All figures are for illustration purpose only, and the number/type of terminals may vary.

All quantities are single unless otherwise noted.