




# Z1182 SOLIDS INTERCEPTOR OPERATION AND MAINTENANCE INSTRUCTIONS

Dimensional Data (inches and [ mm ]) are Subject to Manufacturing Tolerances and Change Without Notice



### **SIZING**

The Z1182 side access stainless steel solids interceptor is designed for suspended or under sink installations where there are height restrictions for a top removal solids interceptor. This unit is furnished with a 2 [51] no-hub high inlet and low outlet on each side for left-hand or right-hand installation (Note: Cap the side not used). The interceptor is capable of handling a maximum flow rate of 35 GPM.

### **DESIGN**

The Zurn Z1182 Solids Interceptor is designed to recover food waste from sinks, garbage grinders and dishwashers. This is accomplished through the principal of screening. The food wastes are retained in the inlet side of the unit by a perforated removable drawer.

### **OPERATION**

The waste water flows from the inlet piping into the interceptor, passing through the perforated drawer attached to the gasketed, latching cover, then exits the interceptor to the sanitary drain system. The waste material is trapped in the perforated drawer and not allowed to pass through to the outlet piping of the drain system.

### **MAINTENANCE**

Cleaning should be done on, a regular basis, either before or after the perforated drawer becomes clogged. Remove the drawer and clean out all debris. Hose off the drawer screen. Make certain the sealing gasket is intact and clean. Apply a light coating of oil on the gasket, which helps prevent the gasket from adhering to the drawer and aids in maintaining a complete seal. The perforated drawer should then be placed back in the unit and secured. Efficiency of operation is directly related to the level of maintenance.

**⚠WARNING:** Cancer and Reproductive Harm - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**⚠ADVERTENCIA:** Cáncer y daño reproductivo - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**⚠AVERTISSEMENT:** Cancer et effets néfastes sur la reproduction - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

Zurn Industries, LLC | Specification Drainage Operation  
1801 Pittsburgh Avenue, Erie, PA U.S.A. 16502 · Ph. 855-663-9876, Fax 814-454-7929

In Canada | Zurn Industries Limited  
3544 Nashua Drive, Mississauga, Ontario L4V 1L2 · Ph. 905-405-8272, Fax 905-405-1292

[www.zurn.com](http://www.zurn.com)

Rev. A  
Date: 04/10/2018  
C.N. No. 139851  
Form No. IT77

Page 1 of 1