


Pin-out Tables for ProductionVIEW HD & HD-SDI

Pin-out table for ProductionVIEW HD & HD-SDI Camera Control Ports 1 through 6 - RS-232 on RJ-45 Connectors:

PIN# Signal

- 1) Unused
- 2) Unused
- 3) Unused
- 4) Unused
- 5) Unused
- 6) GND
- 7) TXD (to RXD of camera)
- 8) RXD (from TXD of camera)



Pin-out table for Inputs and Outputs for ProductionVIEW HD:

Pin	RGBHV	YPbPr	Y/C & Composite Adapter Cable
1	Red	Pr	
2	Green	Y	
3	Blue	Pb	
4	ID	-	
5	N/C	-	
6	Red GND	Pr GND	
7	Green GND	Y GND	
8	Blue GND	Pb GND	
9	No Pin	-	
10	GND	-	GND
11	ID	-	Y - Luminance
12	ID	-	C - Chrominance
13	H-Sync	-	
14	V-Sync	-	
15	N/C	-	Composite

