

Internal: Environmental Dust Concern

Dust coming from the HVAC closet door(s) and vents in the apartment.



Dust accumulating in laundry room re-occurs all the time and needs MDE Lead Inspection

