

25-01032224

Location on Service Request

4312 Saint Paul St

Grid :

1040140

LLC:

7121

Descriptive Location and Comments:

Street:

Saint Paul St

Side of Street: N/S

E/S

S/S

W/S



Pole location: 1"

2nd3rd4th5th6th

Other



Direction : N/O

E/O

S/O

W/O



Street or Landmark:

Greenway

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated

11'6"

Aluminum



Missing

12'

Steel

Damaged

25'

Galvanized Steel

Arm/Fixture Missing

30'

Fiberglass

Other

40'

Bolton Hill

Otterbein

Homeland

Wooden

Other

NEEDS
New Base

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head

HPS Vapor

100

6'

Damaged

PMA

Mercury Vapor

150

10'

Missing

Otterbein

Metal Halide

175

15'

Homeland

LED

200

20'

Bolton Hill

Other

250

Other

Victorian Acorn

400

Other

1000

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes

Bolts

☒

Metal

No

Wires

☒

Concrete

Conduit


☒☒

Date:

12/15/2025

Inspector's Signature:

T. Blackman



30 Foot
Aluminum pole
Cobra Henry
LED