

25-01052701

Location on Service Request

100 W. Mulberry St

Grid

3016120

LLC

7855

Descriptive Location and Comments:

Street:

Mulberry St

Side of Street: N/S



E/S

S/S

W/S

Pole location: 1st



2nd

3rd

4th

5th

6th

Other

Direction

: N/O

E/O

S/O

W/O



Street or Landmark:

Cathedral St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated



11'6"

Aluminum



Missing



12'

Steel

Damaged

25'

Galvanized Steel

Arm/Fixture Missing

30'

Fiberglass

Other

40'

Bolton Hill

Other

Otterbein

Homeland

Wooden

Other

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head



HPS Vapor

100

6'

Damaged

PMA

Mercury Vapor

150

10'

Missing

Otterbein

Metal Halide

175

15'

Homeland

LED

200

20'

Bolton Hill

Other

250

Other

Victorian Acorn

400

Other

1000

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes

No



Bolts

Wires

Conduit



Metal

Concrete




Date:

12/15/2025

Inspector's Signature

T. Blackman



30Foot
Aluminum pole
cobra Head
LED