

Ongoing rodent issue, new **COMPLETED** mouse activity on first floor!! The previous repairs and sealing work on the second floor appear to have helped, as I have not seen any new mouse droppings or activity there for about a week.

However, today I found significant mouse droppings on the first floor near the apartment entrance/storage area, which suggests the rodent issue has not been fully resolved and that there are still active entry points elsewhere in the unit/building structure.

This is an ongoing rodent infestation issue that requires additional inspection and sealing, especially around the first floor entrance, storage area, walls, floor gaps, pipes, and any possible structural openings.

Please send maintenance to inspect and properly seal all potential entry points, and arrange additional pest control treatment as needed.

This issue has already been reported several times previously.

Requested by You on 05/18/26

Maintenance Request #14296-1