


BaltimoreLink Sign and Stop Modifications: July 2026



Actions Needed:

1. Install new supports at [D] and [E].
2. Remove existing bus stop sign (3260) at [A].
3. Install new regulatory sign on existing support at [B].
4. Remove existing parking regulation sign at [C].
5. Install new bus stop sign (3260) at [D].
6. Install new secondary sign at [E].

Comments:

Five (5) unrestricted parking spaces will no longer be available (shaded in red).

Photo:



Issue Number:	# 516
Stop ID:	# 3260
Stop Name:	CLIFTON AVE & MOUNT HOLLY wb mid
Sign Batch:	
Justification Code:	Relocation
Implementation:	July 2026