



Nilfisk




128336070

Kornmarksvej 1|DK-2605 Broendby|Denmark|Tel.: (+45) 4323 8100

Quick Start Guide - Premium 180 / Premium 190

Caution: Read the instructions before using the machine




Premium 180 / Premium 190


A




1




2







3



4




A




A






9



10




11






12





13



B




1




MAX
1 MPa/10 bar

MAX
40°



2




3




B




4




5



6




7




B




8





9



10





11



B



12



13




ROUGH NOZZLE


GENTLE NOZZLE



HARD SURFACES ONLY



14




B





15

MAX




360° x 1,5


MIN



16



MIN




MAX


B




17




18



19





20



B





21




22



23




MIN







MAX


C




1




2



3




C




4


4.1




4.2



5




MAX 2min




6


6.1




6.2



6.3



6.4



7




D

⏸ >5min




1




2


2.1






2.2



2.3



E




E




5


5.1




5.2




6



7



8




F




1


1.1



1.2




2




3


3.1



3.2




4




F



5




6




7

7.1



7.2



7.3

