

SERVICE RECORD UNIT # 1115 KOLBELCO 65 TON SERIAL # GG00082	EQUIPPED WITH FAA LIGHTS		KOB-7065-0001 BASE @ 20'	KOB-7065-0002 10' MID	KOB-7065-0003 20' MID	KOB-7065-0004 30' MID	KOB-7065-0005 30' MID	KOB-7065-0006 POINT @ 20'
12/13/2008	REPLACED HYD. HOSE SEE PO GB11566							
03/17/09 @ 1,113 HOURS	REPLACE PUMP COVER O- RING							
05/04/09 @ 1,313 HOURS	INSTALLED NEW HYD. PUMP SEE PO 20783							
05/19/09 @ 1,363 HOURS	REPLACED RIGHT REAR TRACK ROLLER	TIGHTEN BOTH TRACKS						
09/03/09 @ 1,603 HOURS	REPLACED STARTER							
10/27/09 @ 1,932 HOURS	REPLACED 4 BOOM LACING IN 20' BOOM SECTION, AFTER THE CRANE BOOMED DOWN OVER A WELDER							
11/04/09 @ 1,968 HOURS	REPLACED FUEL INJECTORS REPLACE TRANSFER PUMP	REBUILT RADIATOR SEE PO 12050						
8/30/2010	REPAIRED BOOM LACING							
09/08/2010 @ 2,518 HOURS	ADJUSTED BOOM DOGS							
10/21/2010 @ 2,617 HOURS	RELINED BRAKES ON THE SECOND DRUM SEE PO GB12548	INSTALLED NEW CLUTCHES & BRAKES ON REAR DRUM	REPLACED SENSING VALVES ON BOTH DRUMS	REPLACED PINS ON BOTH BRAKE PEDALS				

10/29/2010 @ 2,617 HOURS	REBUILT BRAKE VALVES FOR BOTH MAIN, AND AUX. DRUM SEE PO 12547		
2/25/2011	REPLACED BECKET PIN WITH A THREADED PIN		
2/28/2011	REPLACED BOTH BATTERIES		
3/10/2011	INSTALLED NEW LINING ON SECOND LINE HOIST CLUTCH SEE PO GB12704, & GB12716		
4/4/2011	REPLACED BOTH TOP, AND FRONT WIPERS SEE PO GB12741		
03/18/2011 @ 6,045 HOURS	ADJUST BRAKE, AND CLUTCHES ON MAIN DRUM		
4/15/2011	REPAIRED SHEAVE GUARD		
04/25/2011 @ 2,810 HOURS	REPLACED FIRST DIAGONAL TOP LACING ON THE BOOM POINT	INSTALLED NEW BOOM CABLE	INSTALLED NEW BOOM TIMBER
07/22/2011 @ 2,862 HOURS	WELDED EXHAUST BRACKETS		
08/22/2011 @ 2,909 HOURS	REPLACED ALTERNATOR SEE PO GB12899		

09/21/2011 @ 2,950 HOURS	REPAIRED WIPERS	REPLACED WATER FILTER	WELDED CRACKS ON FRAME	ADJUSTED CLUTCHES				
12/13/2011 @ 3,063 HOURS	REPLACED TIP SWITCH FOR THE ATB, THAT WAS JOB DAMAGE 501118							
05/11/2012 @ 3,250 HOURS	OPERATORS SEAT SEE PO GB13126	REPLACED SWING RADIUS FLAGS	TIGHTENED TRACKS	REPAIRED BOOM POINT	REPLACED FIRE EXT.			
05/18/2012 @ 3,265 HOURS	REPAIRED HYD LEAK ON THE LEFT SIDE DRIVE MOTOR	INSTALLED NEW CABLES FOR THE MAIN, & AUX. HOIST DOG SEE PO GB13180						
6/12/2012	PURCHASE THIRD DRUM BRAKE VALVE SEE PO AP13320							
10/22/2012 @ 3,714 HOURS	REPAIRED SHORT IN WIRING							
1/2/2013	PAINTED ENTIRE CRANE & BOOM BASE SEE PO LN22918	PAINT BOOM SECTION SEE PO KH1846, KH1860						
07/07/2013 @ 3,728 HOURS	REBUILT HYD PUMPS	REPLACED INTAKE HYD FILTERS	REPLACED RETURN FILTER	REPLACED PILOT FILTER SEE PO MW13712	REPLACED HYD HOSES TO THE PUMPS	FLUSHED HYD. SYSTEM	CHANGED HYD OIL SEE PO GB13562	REPLACED HYD HOSES ON THE PUMP SEE PO GB13564

03/18/2013 @ 3,728 hours	2000 HOUR SERVICE	CHANGED OIL IN THE TRACK PLANITARIES	CHANGED OIL IN THE DRUM WINCHES	CHANGED OIL IN THE BOOM PLANITARY	CHANGED OIL IN THE SWING PLANITARY	REPAIRED WIPER
04/05/2013 @ 3,758 HOURS	REPAIRED INTERIOR LIGHTS	REPAIRED BOOM LACING				
8/9/2013 @ 4,004 HOURS	REPAIRED TRACK EXTENSION BEAMS, AND LOCKS	REBUILT TRACK ADJUSTING BOLTS SEE PO GB13638				
9/9/2013	REPLACED VALVE COVER GASKET SEE PO SJ67047	REPLACED OIL COOLER COVER GASKET				
1/15/2014 @ 4,046 HOURS	COMPLETE TRACK JOB SEE PO LN23603, GB14018, LN23757	REPAIRED BOOM HOIST DOG	MACHINED TRACK IDLER SEE PO GB14035			
08/01/2014 @ 4,265 HOURS	REPLACED 2 LACING ON BOOM TIP	REPAIRED LEAK ON CONTROL LEVER	REPLACED GREASE ZERT ON FRONT DRUM			
05/15/2015 @ 4/24/2015	INSTALLED BOOM CABLE SEE PO LN24411					
04/23/2015 @ 4,543 HOURS	WELDED TRAVEL LEVER	INSTALLED SHIMS ON THE INSIDE TRACK FRAME				

8/14/2015
 REPLACED
 CABLE IN
 THE AUX
 HOIST WITH
 300' SEE PO
 LN24629

10/16/2015 @ 4,858
 HOURS
 ADJUSTED
 TRACKS
 CHANGED OIL
 IN THE FINAL
 DRIVES

10/20/2015
 CHANGED
 OIL IN THE
 TORQUE
 CONVERTOR

05/31/2016 @ 5,845
 HOURS
 2000 HOUR
 SERVICE
 REPAIRED
 MULTIPLE HYD
 LEAKS
 REPAIRED
 COOLANT LEAK
 STEAMED
 RADIATOR
 REPLACED
 WATER PUMP
 SEE CUMMINS
 INV 804-51372
 CHANGED OIL
 IN ALL
 WINCHES
 CHANGED OIL IN
 THE FINAL DRIVE
 REPLACED
 BUSHING IN
 THE FLEETING
 SHEAVE SEE
 RTL INV
 00040372
 CHANGED
 OIL IN THE
 SWING
 GEAR
 CHANGED
 TRANSMISSION OIL
 REPLACED
 TIMING
 COVER
 GASKET SEE
 CUMMIS INV
 804-51390
 REPLACED
 RADIATOR
 HOSES, SEE
 PETER INV
 5586162825
 REPLACED
 THERMOSTAT

06/07/2016 @ 5,845
 HOURS
 REPLACED
 SERPENTINE
 BELT SEE
 PTER INV
 5586162911,
 5586162825
 REPLACED
 BELT
 TENSIONER
 SEE CUMMINS
 INV 804-51374
 REPLACED
 DOOR GLASS
 SEE SAFE INV
 05165132921
 REPLACED
 STARTER SEE
 DIESEL MACH
 INV 0284701

OIL FILTER	FUEL FILTER	AIR FILTER	FAN BELT	HYD. CHARGE PUMP	STARTER MODEL #	ENGINE SERIAL #	WIRE ROPE MAIN HOIST	AUX HOIST	NO THIRD DRUM	BATTERIES	HYD FILTER 2 EACH WIX- 51524	WATER FILTER WIX-24073	BOOM CABLE 5/8 X 492 FLEX-X 6	IN LINE HYD FILTER KOB YN50V01001S005	O-RING FOR FILTERS KOB 2446U346S5
WIX-51748	DONALDSON- P551329 & P550440	DONALDSON- P181080, & P127315		2437U419F1	8200435/39MT/ CUMMINS C8.3- C250	60302805	7/8"	7/8"	NONE	2 EACH 4D	DONALDSON IN TANK -2 EACH P551142	DONALDSON- P552073			
											PILOT FILTER- KOBELCO 2 EACH R36P0019 PILOT FILTER O- RING-KOBELCO 45Z91D84				

DATE	OIL CHANGE	OIL FILTER	AIR FILTER	FUEL FILTER	HYD FILTERS	SWING GEAR	STEAM RADIATOR	ANNUAL INSP.	MECHANIC
2/7/2009	990 HOURS	990 HOURS							
1/25/2009				940 HOURS					
5/13/2009								5/13/2009	
5/8/2009	1,224 HOURS	1,224 HOURS							

