

94-04 CHEVY S10 PICKUP CENTER CONSOLE LID REPAIR KIT INSTRUCTIONS

Package Contents: (1) Console Lid Reinforcement Plate, (4) Rivets

1. Remove Console Lid from Vehicle

Use a phillips head screwdriver to remove the 2 screws from the hinge that holds the lid on.

2. Mark and Pre-drill the Rivet Holes

Reshape the lid, making sure all the broken pieces (1) are re-aligned and flattened. Push the reinforcement plate into the console lid so that it rests in its final installed position (2).

Mark the hole position through the mounting holes in the plate (3). Remove the plate, and drill the 4 holes into the console lid (4). A 9/64" drill bit is a good size for drilling these holes.

3. Tighten Rivets to Secure the Plate

Place the reinforcement plate into the console lid and line the holes in the plate up with the holes now drilled into the lid. Secure it in place using the provided rivets (5) (6) (7).

In the absence of a rivet tool, screws (not provided) may also be used, but rivets are stronger and create a more professional look.

