



Daikin Multi-Zone Model Number Update



Daikin is updating select R-32 Multi-Zone and AURORA Multi-Zone outdoor unit model numbers with no changes to performance, compatibility, warranty, or accessory fit.

What's Changing?

Daikin has announced a model number update for select R-32 Multi-Zone and AURORA Multi-Zone outdoor units. The only change is to the **last digit of the model number**, which is changing from “9” to “8.”

This is a model number update only. Customers can continue using the updated models with the same compatible indoor units and accessories.

What Stays the Same?

Daikin has confirmed there are no changes to the following:

- Specifications
- Performance
- Compatibility
- Warranty
- Accessory fit

The current models ending in “9” maintain the same indoor unit compatibility as the updated models ending in “8.”

Daikin Multi-Zone Model Number Update	
Previous Daikin Model #	Updated Daikin Model #
3MXT24AVJU9	3MXT24AVJU8
3MXTH24AVJU9	3MXTH24AVJU8
4MXT36AVJU9	4MXT36AVJU8
4MXTH36AVJU9	4MXTH36AVJU8
5MXT40AVJU9	5MXT40AVJU8
5MXTH40AVJU9	5MXTH40AVJU8
5MXM48AVJU9	5MXM48AVJU8

What This Means for Customers

There is no action required beyond noting the updated model numbers. HVAC Distributors will continue to support these Daikin multi-zone systems, and the updated models are intended to maintain the same application and compatibility as the previous versions.

For questions, please contact your local HVAC Distributors branch.