

# TECHNICAL SERVICE BULLETIN

**TSB D-GN-OT-0091**

**Date:** March 11, 2026  
**To:** All Service and Parts Managers  
**From:** Technical Services Department  
**Subject:** **KRP4A98A is replacing KRP4A98**

This Technical Service Bulletin is issued to announce that the **KRP4A98A** mounting adaptor will **replace** the existing **KRP4A98** model.

The mounting adaptor is required to support the installation of the following accessories:

- Wiring Adaptor PCB (KRP1C7x)
- Group Control Adaptor (KRP4A7x)
- Ventilation and Alarm PCB (BRP9A7x)

The replacement adaptor maintains the same application and installation function as the outgoing model.

## **Applicable Indoor Unit Models**

The KRP4A98A adaptor remains compatible with the same indoor unit categories as the previous model, including:

- **R-32 VRV Indoor Units:** FXMA, FXSA
- **R-32 SkyAir Indoor Units:** FBA
- **R-410A VRV Indoor Units:** FXSQ\_TB, FXSQ\_TA, FXMQ\_TB
- **R-410A Mini-split:** FDMQ

If you have technical questions, please call 1-855-DAIKIN1 or e-mail [TechnicalServicesDaikin@daikincomfort.com](mailto:TechnicalServicesDaikin@daikincomfort.com).