

PRODUCT DATA SHEET





PART NUMBER - BLX1FF042: BRAH Electric, aftermarket direct replacement coils for Telemecanique LX1FF042, TeSys F Series, type BLX1F, 42V AC 50Hz, coil suffix code is B5, suitable for use with all 3P and 4P LC1F115, LC1F150, LC2F115, LC2F150 contactors


MAGNETIC COILS PART NO. BLX1FF042

MANUFACTURER	BRAH Electric
SUB-CATEGORY	Coils
FAMILY	TeSys F
TYPE	BLX1F
TYPE FOR	LC1F115, LC1F150, LC2F115, LC2F150
VOLTAGE	42

Warranty: All Products sold by BRAH Electric are guaranteed to be free of defect for a period of one year, under the condition that the product has been installed and operated properly. All items proven defective within the one year period will be replaced by BRAH Electric. In the event that we cannot provide a direct replacement, your monies will be refunded in full. We are not responsible for any consequential losses or damages outside of the defective product as well as any replacements or repairs performed by another party without our written authorization from BRAH Electric.







*NOTE: BRAH ELECTRIC COIL BLX1FF042 IS A DIRECT REPLACEMENT FOR TELEMECANIQUE LX1FF042, TESYS F SERIES, SUITABLE FOR USE WITH ALL 3P AND 4P LC1F115, LC1F150, LC2F115, LC2F150 CONTACTORS.

WWW.BRAHELECTRIC.COM, 855-355-2724

