

viega



6 9 1 5 1 4 9 1 5 6 0 9



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
1	1

Part No
91560

viega



6 9 1 5 1 4 9 1 5 4 5 6



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
1	3/4

Part No
91545

viega



6 9 1 5 1 4 9 1 5 9 0 6



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
2	2

Part No
91590

viega



6 9 1 5 1 4 9 1 5 2 0 3



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
1/2	1/2

Part No
91520

viega



6 9 1 5 1 4 9 1 5 2 5 8



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
1/2	3/4

Part No
91525

viega



6 9 1 5 1 4 9 1 5 4 0 1



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
3/4	3/4

Part No
91540

viega



6 9 1 5 1 4 9 1 5 4 1 8



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
3/4	1/2

Part No
91541

viega



6 9 1 5 1 4 9 1 5 7 0 8



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
1 1/4	1 1/4

Part No
91570

viega



6 9 1 5 1 4 9 1 5 8 0 7



Viegaflex Press adapter,
Zero Lead, Bronze, Model 2812ZL

P	FPT
1 1/2	1 1/2

Part No
91580

viega



6 9 1 5 1 4 6 9 6 2 7 0



Viegaflex Press adapter,
Smart Connect technology,
Bronze, Model 2813PNG

P1	P2
5/8	1/2

Part No
69627