

viiega



6 9 1 5 1 4 9 2 4 0 6 9



**Viega PureFlow Press 90° stub-out,
Brazed copper, Model 2820.1ZL**

P	FTG (CTS)	L1 [in]	L2 [in]
3/8	1/2	3 1/2	8

Part No
92406

viiega



6 9 1 5 1 4 9 2 4 2 1 2



**Viega PureFlow Press 90° stub-out,
Brazed copper, Model 2820.1ZL**

P	FTG (CTS)	L1 [in]	L2 [in]
1/2	1/2	3 1/2	8

Part No
92421

viiega



6 9 1 5 1 4 9 2 4 4 1 0



**Viega PureFlow Press 90° stub-out,
Brazed copper, Model 2820.1ZL**

P	FTG (CTS)	L1 [in]	L2 [in]
3/4	3/4	3 1/2	8

Part No
92441

viiega



6 9 1 5 1 4 9 2 3 0 5 5



**Viega PureFlow Press 90° stub-out,
Brazed copper, Model 2820.4ZL**

P	FTG (CTS)	L1 [in]	L2 [in]
3/8	1/2	3 1/2	8

Part No
92305

viiega



6 9 1 5 1 4 9 2 3 2 1 5



**Viega PureFlow Press 90° stub-out,
Brazed copper, Model 2820.4ZL**

P	FTG (CTS)	L1 [in]	L2 [in]
1/2	1/2	3 1/2	8

Part No
92321

viiega



6 9 1 5 1 4 9 2 6 0 9 4



**Viega PureFlow Press stub-out,
Brazed copper, Model 2820.2ZL**

P	FTG (CTS)	L [in]
1/2	1/2	8

Part No
92609

viiega



6 9 1 5 1 4 9 2 6 1 6 2



**Viega PureFlow Press stub-out,
Brazed copper, Model 2820.2ZL**

P	FTG (CTS)	L [in]
1/2	1/2	15

Part No
92616

viiega



6 9 1 5 1 4 4 9 3 2 4 4



**Viega PureFlow Press lav adapter,
Smart Connect technology, Poly-
mer, Model V5613.3**

P	Lav
3/8	1/2

Part No
49324

viiega



6 9 1 5 1 4 4 9 3 3 3 6



**Viega PureFlow Press lav adapter,
Smart Connect technology, Poly-
mer, Model V5613.3**

P	Lav
1/2	1/2

Part No
49333

viiega



6 9 1 5 1 4 4 9 3 4 4 2



**Viega PureFlow Press lav adapter,
Smart Connect technology, Poly-
mer, Model V5613.3**

P	Lav
3/4	3/4

Part No
49344