

viega



6 9 1 5 1 4 4 9 1 4 4 8



Viega PureFlow Press adapter

Smart Connect Technology

Zero Lead, Polymer, Model V5644ZL


WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov
49144

P	FPT
1	1/2

viega



6 9 1 5 1 4 4 9 1 3 2 5



Viega PureFlow Press adapter

Smart Connect Technology

Zero Lead, Polymer, Model V5644ZL


WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov
49132

P	FPT
3/4	1/2

viega



6 9 1 5 1 4 4 9 1 5 0 9



Viega PureFlow Press replacement bracket, Plastic, Model V5643ZL

WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov
49150

viega



6 9 1 5 1 4 9 2 2 2 1 8



Viega PureFlow Press 90° tub elbow, Brazed copper, Model 2820.0ZL


P	FTG (CTS)	L1 [in]	L2 [in]
1/2	1/2	3	6

Part No
92221

viega



6 9 1 5 1 4 9 2 4 4 6 5



Viega PureFlow Press 90° stub-out, Brazed copper, Model 2820.1ZL


P	FTG (CTS)	L1 [in]	L2 [in]
1	1	6	8

Part No
92446

viega



6 9 1 5 1 4 9 2 4 4 1 0



Viega PureFlow Press 90° stub-out, Brazed copper, Model 2820.1ZL


P	FTG (CTS)	L1 [in]	L2 [in]
3/4	3/4	4	8

Part No
92441

viega



6 9 1 5 1 4 9 2 4 0 6 9



Viega PureFlow Press 90° stub-out, Brazed copper, Model 2820.1ZL


P	FTG (CTS)	L1 [in]	L2 [in]
3/8	1/2	3 1/2	8

Part No
92406

viega



6 9 1 5 1 4 9 2 4 2 1 2



Viega PureFlow Press 90° stub-out, Brazed copper, Model 2820.1ZL


P	FTG (CTS)	L1 [in]	L2 [in]
1/2	1/2	3 1/2	8

Part No
92421

viega



6 9 1 5 1 4 9 2 3 0 5 5



Viega PureFlow Press 90° stub-out, Brazed copper, Model 2820.4ZL


P	FTG (CTS)	L1 [in]	L2 [in]
3/8	1/2	3 1/2	8

Part No
92305

viega



6 9 1 5 1 4 9 2 3 2 1 5



Viega PureFlow Press 90° stub-out, Brazed copper, Model 2820.4ZL

P	FTG (CTS)	L1 [in]	L2 [in]
1/2	1/2	3 1/2	8

Part No
92321