


viega



6 9 1 5 1 4 4 9 4 1 6 6



WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov


Part No
49416

P	Supply
1	1

viega



6 9 1 5 1 4 9 6 1 6 1 3



Viega PureFlow Press supply adapter
Zero Lead, Bronze, Model 2877.8ZL

P	Supply
1	1

Part No
96161

viega



6 9 1 5 1 4 4 6 3 4 6 9



Viega PureFlow ManaBloc supply adapter
Zero Lead, Brass, Model V5032ZL


CTS	Supply
3/4	1

Part No
46346

viega



6 9 1 5 1 4 4 6 6 4 6 0



Viega PureFlow ManaBloc supply adapter
Zero Lead, Brass, Model V5033ZL

MPT	Supply
3/4	1

Part No
46646

viega



6 9 1 5 1 4 4 6 4 1 4 5



WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov

Viega PureFlow Crimp supply adapter
Zero Lead, Brass, Model V5034ZL


Crimp	Supply
3/4	1

Part No
46414

viega



6 9 1 5 1 4 4 9 4 1 4 2



WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov


Part No
49414

P	Supply
3/4	1

viega



6 9 1 5 1 4 9 6 1 4 1 5



Viega PureFlow Press supply adapter
Zero Lead, Bronze, Model 2877.8ZL


P	Supply
3/4	1

Part No
96141

viega



6 9 1 5 1 4 4 6 6 5 6 9



Viega PureFlow ManaBloc supply adapter
Zero Lead, Brass, Model V5033ZL


MPT	Supply
1	1

Part No
46656

viega



6 9 1 5 1 4 4 6 4 1 6 9



WARNING:
CANCER AND
REPRODUCTIVE HARM-
www.P65Warnings.ca.gov

Viega PureFlow Crimp supply adapter
Zero Lead, Brass, Model V5034ZL

Crimp	Supply
1	1

Part No
46416

viega



6 9 1 5 1 4 5 0 2 6 9 4



Viega ManaBloc supply adapter
Zero Lead, Brass, Model V5035ZL

PB	Supply
1	1

Part No
50269