


Q#4.0
CORRECT.
YES UNFACTORED.



Please verify if loads are shown as
Shear (+), Uplift (-) (TYP)

Please also verify that loads are
unfactored (ASD) as indicated on
the general notes

Please verify that
these are Type D
connections (TYP)

Q#5.)
PLEASE EXPAND ON WHAT
YOUR DOING HERE IN THE
SHOP DRAWINGS, FOR SCA
REVIEW