

PRODUCT NUMBER: 1015280

Hygiene Kit - Impact Sport



Översikt

Reference Number

1015280

Product Type

Hörselskydd

Range

Earmuffs

Brand

Howard Leight by Honeywell

Brand formerly known as

BILSOM

Industry

- Army - Defence
- ATEX environment
- Automotive and Part Manufacturer
- Aviation
- Building and Construction
- Catering
- Chemical Industries
- Administration
- Agriculture
- Energy or Electricity
- Fire Protection brigades
- Fishing
- Food Industries
- Foundry
- Glass Industries
- Green Spaces
- Homeland defense
- Industrial Cleaning
- Iron and steel industry
- Logistics
- Maintenance
- Medical and Pharmaceutical
- Metal steel
- Mining and Quarrying
- Offshore
- Paper Industries
- Petro-chemical
- Printing Industries
- Services
- Telecoms
- Textile Industries
- Transportation
- Utilities
- Water treatment
- Welding
- Wood Industries
- Laboratory
- Ship Building
- Industry

Product Use

Hygiene Kit for Impact Sport

Features & Benefits

Feature

Extends performance and lifetime of earmuff Recommended replacement every 6 months with general use, more frequently with general usage Snap-in ear cushions for quick and easy replacement

Benefit

Includes one pair of snap-in ear cushions and one pair of foam earcup inserts for Bilsom Impact Sport Earmuff only.

Technical Description

Earmuff Construction

None

Other Material

PVC foil, PUR-E, Polyester

Dielectric

Yes

Color

Black

Sound Amplification

No

AM/FM Radio

No

Automatic Shut-Off Function

No


Audio Input Jack

No

Hi-Visibility

No


Certifications


 E.C. Declaration of Conformity

EC Category PPE

0

Trycksaker & dokument

 E.C. Declaration of Conformity

 PIC SKU - Pictures

<http://www.honeywellsafety.com/assets/0/324/500/51887/17a6c24b93914711977d85f6014da240.jpg>

Foton & bilder

Det finns inga bilder för närvarande.

Maintenance

Life Cycle

Cushions should be replaced periodically to retain maximum attenuation. Use the following as a guideline for replacement of ear cushions and insert foam. General use and wear - Ear cushions and foam inserts should be replaced at least every 6 months. Heavy use or wear in humid/extreme climates - Ear cushions and foam inserts should be replaced at least every 3 months. Cracking or leakage is visible - replace ear cushions and foam inserts immediately.

Packaging

EAN Code

7312550152805

Honeywell

Välj region/land

© 2011 Honeywell International Inc.