


VR030: VR15P, VR16L9, 2XVR31, 2XVR32, VR1902
 VR940: VR937, VR938, VR939



VOLA A/S
 Lunavej 2
 DK-8700 Horsens
 Tlf : + 45 7023 5500
 Fax: + 45 7023 5511
 sales@vola.com
 www.vola.com

VOLA 030

Dato


Jan. 05

Rev.


3

Blad

SB 12



VR030: VR15S, VR16S, VR22, 2XVR31, 2XVR32, VR1902



VOLA A/S
Lunavej 2
DK-8700 Horsens
Tlf : + 45 7023 5500
Fax: + 45 7023 5511
sales@vola.com
www.vola.com

VOLA 030

Dato


Okt. 00

Rev.


2

Blad

SB 12



VR030: VR15S, VR16S, VR22, 2XVR31, 2XVR32, VR1902



VOLA A/S
Lunavej 2
DK-8700 Horsens
Tlf : + 45 7023 5500
Fax: + 45 7023 5511
sales@vola.com
www.vola.com

VOLA 030

Dato


Feb. 96

Rev.


1

Blad

SB 12



VR030: VR15S, VR16S, VR22, 2XVR31, 2XVR32, VR1902



VOLA A/S
 Lunavej 2
 DK-8700 Horsens
 Tlf : + 45 7023 5500
 Fax: + 45 7023 5511
 sales@vola.com
 www.vola.com

VOLA 030

Dato
 Jan. 84

Rev.
 0

Blad
 SB 12