

A (x1)

B (x1)

C (x1)

D (x1)

E (x1)

F (x1)

G (x1)

H (x1)
M8x20

I (x2)
M6x10

J (x1)
4mm

K (x1)
5mm

M-A (x4)
M4x12

M-B (x4)
M5x12

M-C (x4)
D5

1

10-40mm

10-40mm

OR

10-35mm

OR

35-80mm

10-40mm

OR

10-40mm

OR

10-35mm

OR

35-80mm

2

±180°

Arm can rotate without stopping.

1

±90°

Arm can rotate 180°.

3

TOP

4

TOP