

ENVIRONMENTAL METER

Temperature & Humidity Meter with Dew Point VA8010

VA8010



The meter is a temperature and humidity measuring instrument. It is normally used to measure the humidity and temperature in offices, storerooms, buildings and greenhouses.

Specifications

	VA8010
Measurement Parameters	°C , °F ,%RH(relative humidity),td (dew point temperature)
Measuring Range	-10~+50°C ,+14~+122 °F ,0~100%RH
Accuracy	±1.0°C ,±1.8 °F ,±3%RH (5~95%RH)
Resolution	0.1°C ,0.1 °F ;0.1%RH
Sample Rate	1 time sec

Features

Display	4 digits LCD Display
Data Hold	√
Dew point temperature	√
Auto Power Off	About 20min
Power	1.5V Battery (AAA)X3
Size	121x60x30 mm
Weight	~ 180g

Accessories Included

Free 1.5V x3 AAA batteries
Free protect cover
Free protective carrying case
Free Wrist / String
User Manual

Fastron
Electronics

- Power Semiconductors
- Electrical Measurement
- Process Control

9B Lakewood Blvd
Braeside VIC 3195 Australia

Web: www.fastron.com.au
Email: sales@fastron.com.au
Telephone: + 61- 3 - 97635155
Facsimile: + 61- 3 - 97635206