

Loading Tools into the FlexCart's Front Tool Compartment.

The tools contained in this box are for the tool compartment located at the front of the FlexCart. We have provided the tools to you separately from the cart because the process of loading them into the cart provides a valuable introduction to the FlexCart Engineering Cart and the tools it carries.

Step 1: Empty the box:

Carefully empty the contents of the box onto a large table.



Step 2: Layout tools neatly on the table:

Remove each tool from its packaging and lay all of the unpackaged tools neatly on the table.



Step 3: Load tools into the pockets:

Starting on the left side of the tool compartment door, read the pocket label, locate that tool on the table and insert it into the pocket. Work your way across the top row of pockets and then across the bottom row filling each pocket with the proper tool.



The below picture shows the best way to insert each tool.



**If you have any questions
please call:
614-348-2517**