# 300XAC Series ( @ CROHS)

# Modular AC Power Sources

Our 300XAC Series modular AC power sources incorporate the latest in modular technology, making them ideal for the most demanding applications. These versatile AC power sources can be configured for 1Ø stand-alone operation or linked together for up to 16.2 kVA of AC power in 1Ø or up to 18 kVA of AC power in 3Ø output configurations.



# **Features**

- Modular design allows operator to connect up to 3 instruments together for 1Ø or 3Ø applications requiring up to 18kVA of AC power
- Configure 2 sources for 1Ø/2W output voltages up to 600VAC
- 50 built-in memory locations with 9 test steps
- Standard DC output capability
- Transient feature simulates voltage variations, brownouts, and transient voltage conditions
- Constant current output with over current fold back feature
- Rack mount handle kit included

# Standard

USB/RS-232 Interface

# **Options**

- Grounded Neutral
- Ethernet Interface
- GPIB Interface
- Linking Card
- 7 Remote Memories

# PowerTRAC AVAILABLE



# **Applicable**











# **APT Benefits**





# The Modular AC Source Advantage

# What is a modular AC power source?

We use the term modular to define the capability of our 300XAC Series to be interconnected. The interconnection among up to three individual 300XAC Series Power Sources, allows for higher power outputs and different power configurations than an individual instrument could allow for Parallel or Polyphase modes.

### What is Parallel mode?

Parallel mode allows the operator to increase the output current of the system by a factor of 2 or 3 depending on the number of sources that are interconnected.

# What is Polyphase mode?

Polyphase mode allows the operator to increase the total power output of the system as well as change the output power configuration of the system.



# **Advantages**

### **SmartDETECT**

This exclusive feature automatically determines how many power sources are linked together. After the check is completed the 300XAC Series will automatically change the programming output function based on the number of linked sources.

### **SmartCONFIG Feature**

This exclusive feature allows the operator to easily change the output of the linked sources to Parallel or Polyphase mode with the push of a button.

### Master/Slave Relationship

The master/slave relationship between linked 300XAC instruments synchronizes the firmware of each power source so the output and phase angle separation is regulated. It also gives the operator the capability to program parameters for all linked sources from the front panel of the master instrument.

### **Exclusive Linking Card (option 08)**

With the Linking Card option installed, up to three 300XAC instruments can be interconnected for Parallel or Polyphase output.

# **Benefits**

- Easy to change from 1Ø to 3Ø output
- No need to have separate sources for 1Ø to 3Ø applications
- Allows for future expansion if power requirements change
- Greater mobility of the AC power sources
- Ability to generate 3Ø power if only 1Ø is available

# Make Linking Your 300XAC A Breeze.

Download our Linking Guide at aptsources.com/300XAC

toll-free **+1-877-322-7693** 

# Specifications – 300XAC Series

INPUT		310XAC	320XAC	340XAC	360XAC		
Phase			1Ø		1Ø or 3Ø		
<b>V</b> oltage		100 - 240 VAC ±10%		200 - 240 VAC ±10%	1Ø: 200 - 240 VAC ±10% 3Ø3W: 200 - 240 VAC ±10% 3Ø4W: 346 - 416 VAC ±10%		
Frequency				47 - 63 Hz			
OUTPUT							
/oltage				5 - 300 V			
Max Power		1 kVA	1 kVA 2 kVA 4 kVA		6 kVA		
Max Current 1Ø	0 - 150 V	9.2 A @ ≤110 V	18.4 A @ ≤110 V	36.8 A @ ≤110 V	55.2 A @ ≤110 V		
	0 - 300 V	4.6 A @ ≤220 V	9.2 A @ ≤220 V	18.4 A @ ≤220 V	27.6A @ ≤220 V		
hase				nase Linking for 1Ø3W or 3Ø4W)			
requency		40.0 - 1000 Hz					
HD				(Resistive Load)			
rest Factor			Inrush CF ≥3 at 110 V,	Continuous Current CF ≥3 at 110 V			
ine Regulation		± 0.1 V					
oad Regulation	TACE			± 0.5 V			
OC OUTPUT VOL	IAGE			5 420 1/			
/oltage		1000 W	2000 W	5 - 420 V	600014/		
Nax Power Nax Current 1Ø	0 - 210 V	4.8 A	2000 W 9.6 A	4000 W 19.2 A	6000 W 28.8 A		
nax Current ID	0 - 210 V 0 - 420 V	2.4 A	9.6 A 4.8 A	9.6 A	28.8 A 14.4 A		
ople & Noise (Peak to Peak)		<3.		2.07	<4.0 V		
MEASUREMENT	in to really	15.	· ·				
	Range			0.0 - 400.0 V			
Voltage	Accuracy	± (1% of reading + 2 counts) >5 V ± (1% of reading + 5 counts) >5 V					
		2.00 - 1000 Hz					
requency	Range Accuracy			.1 Hz, 501 - 1000 Hz ± 0.2 Hz			
	Range	0.005 A - 13.00 A	0.005 A - 26.00 A	0.05 A - 52.00 A	0.05 A - 78.00 A		
Current (RMS)	Accuracy	± (1% of readin	H0 - 100 Hz, ± (1% of reading + 5 counts) ading + 5 counts) @ 501 - 1000 Hz >0.2 /				
	Range	0.0 A - 38.0 A	0.0 A - 76.0 A	0.0 A - 152 A	0.0 A - 228 A		
Current Peak	Accuracy		± (1% of	freading + 5 counts)			
	Range	0.0 W - 1300 W	0.0 W - 2600 W	0.0 W - 5200 W			
ower	L	± (2% of reading + 1			g + 5 counts) at PF ≥0.2		
	Accuracy	_ (2/0 01100001119 1 1		ling + 5 counts) at PF ≥0.2	9 . 5 . 5 . 5 . 5 . 5 . 5 . 5 . 5 . 5 .		
		0.01/4 12001/4		-	0.01/470001/4		
Power Apparent (VA)	Range	0.0 VA - 1300 VA	0.0 VA - 2600 VA	0.0 VA - 5200 VA	0.0 VA - 7800 VA		
	Calculated Formula	0.01/45		Calculated value			
Power Reactive (Q)	Range	0.0 VAR - 1300 VAR	0.0 VAR - 2600 VAR				
(2)	Calculated Formula		W) <sup>2</sup> , Calculated value				
ower Factor	Range	0.000 - 1.000					
	Calculated Formula	W/VA, Calculated and displayed to three significant digits					
Crest Factor	Range			0.0 - 10.0			
arest ractor	Accuracy	A peak / Arms, Calculated and displayed to two significant digits					
OPTIONS							
Frounded Neutral	Option 2			All Models			
PIB Interface	Option 3	All Models					
7 Remote Memory Option 4		All Models					
Ethernet Interface Option 6		All Models					
inking Card	Option 8			All Models			
GENERAL							
	ment		0 - 41	0°C / 20 - 80% RH			
Operation Environn							
	x D)	16.92 x 5.26 x 20.87 in	16.92 x 5.26 x 20.87 in	16.92 x 10.51 x 19.69 in	16.92 x 15.77 x 19.69 in		
Operation Environn  Dimensions (W×H	x D)	16.92 x 5.26 x 20.87 in 430 x 133.5 x 530 mm	16.92 x 5.26 x 20.87 in 430 x 133.5 x 530 mm	16.92 x 10.51 x 19.69 in 430 x 267 x 500 mm	16.92 x 15.77 x 19.69 in 430 x 400.5 x 500 mm		

# Specifications - 300XAC Series

Linking Parallel	Linking Parallel Output 1Ø2W		310XAC	320XAC	340XAC	360XAC		
Linked Unit				2 - 3 Uni	its, 1Ø2W (L1 - N)			
Voltage Phase		5-300 V						
Power Max	#11-24-	2	1.8 kVA	3.6 kVA	7.2 kVA	10.8 kVA		
	# Units	3	2.7 kVA	5.4 kVA	10.8 K 10.8 kVAA A	16.2 kVA		
Max Current	0 - 150 V	L(2)	14.72 A @ 20 V -110 V	29.44 A @ 20 V -110 V	58.88 A @ 20V - 110 V	88.32 A @ 20 V - 110 V		
		L(3)	22.08 A @ 20 V - 110 V	44.16 A @ 20 V - 110 V	88.32 A @ 20 V - 110 V	132.48 A @ 20 V - 110 V		
Line (RMS)	0 - 300 V	H(2)	7.36 A @ 20 V - 220 V	14.72 A @ 20 V - 220 V	29.44 A @ 20 V - 220 V	44.16 A @ 20 V - 220 V		
		H(3)	11.04 A @ 20 V - 220 V	22.08 A @ 20 V - 220 V	44.16 A @ 20 V - 220 V	66.24 A @ 20 V - 220 V		
Linking Polyphas	e Output	1Ø3W	310XAC	320XAC	340XAC	360XAC		
Linked Units		2 Units @ 180°, 1Ø3W (L1-L2 - N)						
Voltage	Phase		10 - 600 V					
	Line				5 - 300 V			
Power	Max		2 kVA	4 kVA	8 kVA	12 kVA		
Max Current Phase	0 - 300 V	L(1)	9.2 A @ ≤110 V	18.4 A @ ≤110 V	36.8 A @ ≤110 V	55.2 A @ ≤110 V		
	0 - 600 V	H(1)	4.6 A @ ≤220 V	9.2 A @ ≤220 V	18.4 A @ ≤220 V	27.6 A @ ≤220 V		
Max Current Line	0 - 300 V	L(2)	9.2 A @ ≤220 V	18.4 A @ ≤220 V	36.8 A @ ≤220 V	55.2 A @ ≤220 V		
	0-600 V	H(2)	4.6 A @ ≤440 V	9.2 A @ ≤440 V	18.4 A @ ≤440 V	27.6 A @ ≤440 V		
Linking Polyphas	e Output	3Ø4W	310XAC	320XAC	340XAC	360XAC		
Linked Units		3 Units @ 120°, 3Ø4W (L1-L2-L3 - N)						
Voltage	Phase		5 - 300 V					
	Line			5 - 520 V				
Power	Max		3 kVA	6 kVA	12 kVA	18 kVA		
Max Current Phase	0 - 150 V	L(1)	9.2 A @ ≤110 V	18.4 A @ ≤110 V	36.8 A @ ≤110 V	55.2 A @ ≤110 V		
	0 - 300 V	H(1)	4.6 A @ ≤220 V	9.2 A @ ≤220 V	18.4 A @ ≤220 V	27.6 A @ ≤220 V		
Max Current Line	0 - 150 V	L(3)	9.2 A @ ≤190.5 V	18.4 A @ ≤190.5 V	36.8 A @ ≤190.5 V	55.2 A @ ≤190.5 V		
	0 - 300 V	H(3)	4.6 A @ ≤381 V	9.2 A @ ≤381 V	18.4 A @ ≤381 V	27.6 A @ ≤381 V		
Max Current Phase Delta	0 - 260 V	L(3)	5.31 A @ ≤190.5 V	10.62 A @ ≤190.5 V	21.24 A @ ≤190.5 V	31.87 A @ ≤190.5 V		
	0 - 520 V	H(3)	2.65 A @ ≤381 V	5.31 A @ ≤381 V	10.62 A @ ≤381 V	15.93 A @ ≤381 V		
Linking Parallel D	C Output	1Ø2W	310XAC	320XAC	340XAC	360XAC		
Linked Units					ts, 1Ø2W (L1 - N )			
Voltage Power	Line		5 - 420 V					
Power Max	# Units	2	1.8 kVA	3.6 kVA	7.2 kVA	10.8 kVA		
		3	2.7 kVA	5.4 kVA	10.8 kVA	16.2 kVA		
Max Current	0 - 210 V	L(2)	7.68 A @ 50 V - 210 V	15.36 A @ 50 V - 210 V	30.72 A @ 50 V - 210 V	46.08 A @ 50 V - 210 V		
Line		L(3)	11.52 A @ 50 V - 210 V	23.04 A @ 50 V - 210 V	46.08 A @ 50 V - 210 V	69.12 A @ 50 V - 210 V		
	0 - 420 V	H(2)	3.84 A @ 50 V - 420 V	7.68 A @ 50 V - 420 V	15.36 A @ 50 V - 420 V	23.04 A @ 50 V - 420 V		
		H(3)	5.76 A @ 50 V - 420 V	11.52 A @ 50 V - 420 V	23.04 A @ 50 V - 420 V	34.56 A @ 50 V - 420 V		

toll-free +1-877-322-7693

# Specifications – 300XAC Series

Measurement (To Linking Parallel 1			310XAC	320XAC	340XAC	360XAC		
Voltage	Range			0.0	0 - 400.0 V			
	Accuracy		$\pm$ (1% of reading + 2 counts) >5 V $\pm$ (1% of reading + 5 counts) >5 V					
requency Range		0.0 - 1000.0 Hz						
,	Accuracy	L	± 0.1 Hz @ 0.0 - 500 Hz					
		Н	± 0.2 Hz @ 501 - 1000 Hz					
Current (RMS)	Range	2	0.00 A - 26.00 A	0.00 A - 52.00 A	0.00 A - 104.0 A	0.00 A - 156.0 A		
		3	0.00 A - 39.00 A	0.00 A - 78.00 A	0.00 A - 156.0 A	0.00 A - 234.0 A		
	Accuracy	L		ounts) x # of Linked Units & Current is >1.0 A	± (1.5% of reading +15 counts) x Link Units @ 40.0 - 70.0 Hz and Current (RMS) >2.00 A, ± (1.5%	± (1.5% of reading +15 counts) x Link Units @ 40.0 - 70.0 Hz and Current (RMS) >3.00 A, ± (1.5% of reading +15 counts) x Link Units @ 70.1 - 1000 Hz, and Current (RMS) >15.00 A		
		Н		ounts) x # of Linked Units Current is >5.00 A	of reading +15 counts) x Link Units @ 70.1 - 1000 Hz, and Current (RMS) >10.00 A			
Power (W)	Range	2	0 W - 2600 W	0 W - 5200 W	0 W -10400 W	0 W - 15600 W		
		3	0 W - 3900 W	0 W - 7800 W	0 W - 15600 W	0 W - 23400 W		
	Accuracy		$\pm$ (2% of reading + 10 counts) x (# of Linked Units) at PF ≥0.2, 40 - 500 Hz, and Current >5.0 A $\pm$ (2% of reading + 10 counts) x (# of Linked Units) at PF ≥0.3, 501 - 1000 Hz, and Current >5.0 A					
Power Apparent (VA)	Range	2	0 W - 2600 VA	0 W - 5200 VA	0 W -10400 VA	0 W - 15600 VA		
		3	0 W - 3900 VA	0 W - 7800 VA	0 W - 15600 VA	0 W - 23400 VA		
	Accuracy		V x A, Calculated Value					
Power Reactive (Q)	Range	2	0 W - 2600 VA	0 W - 5200 VA	0 W -10400 VA	0 W - 15600 VA		
		3	0 W - 3900 VA	0 W - 7800 VA	0 W - 15600 VA	0 W - 23400 VA		
	Accuracy		$\sqrt{(VA)^2 - (W)^2}$ , Calculated Value					
Power Factor	Range		0 - 1.000					
	Accuracy		W / VA, Calculated and displayed to three significant digits					
Measurement (To Linking Polyphas			310XAC	320XAC	340XAC	360XAC		
Voltage	Range	2		ge + L2 Voltage				
	Accuracy		Summation of linked sources, Calculated and displayed to one significant digit					
Frequency	Range		0.0 - 1000.0 Hz					
	Accuracy	L	± 0.1 Hz @ 0.0 - 500 Hz					
		Н	± 0.2 Hz @ 501 - 1000 Hz					
Current (RMS)	Range	2	(L1 Current + L2 Current)/2					
	Accuracy		$\pm$ (1% of reading + 5 counts) at 40 - 70 Hz $\pm$ (1% of reading + 5 counts) at 70.1 - 500 Hz, and output current (RMS) >0.200 A $\pm$ (1% of reading + 5 counts) at 501 - 1000 Hz, and output current (RMS) >0.300 A					
Power (W)	Range	2	L1 Power + L2 Power					
	Accuracy	2		L1 Power + L2 P	ower, Calculated Value			
Power Apparent	Range	2	L1 VA + L2 VA					
(VA)	Accuracy	2		L1 VA + L2 V	A, Calculated Value			
Power Reactive (Q)	Range	2	L1 VAR + L2 VAR					
,	Accuracy	2	L1 VAR + L2 VAR, Calculated Value					
Power Factor	Range				0 - 1.000			
	Accuracy		0.1	(L1 P + L2 P) / (L1 VA + L2 VA), Calculated and displayed to three significant digits				

# Specifications - 300XAC Series

Measurement (To Linking Polyphas			310XAC	320XAC	340XAC		360XAC	
Voltage	Range		(A+B+C)/3					
	Accuracy		(A+B+C)/3, Calculated and displayed to one significant digit					
Frequency	Range		0.0 - 1000.0 Hz					
	Accuracy L		± 0.1 Hz @ 0.0 - 500 Hz					
		Н	± 0.2 Hz @ 501 - 1000 Hz					
Current (RMS)	Range		(A+B+C)/3					
	Accuracy		$\pm$ (1% of reading + 5 counts) at 40 - 70 Hz $\pm$ (1% of reading + 5 counts) at 70.1 - 500 Hz, and output current (RMS) >0.200 A $\pm$ (1% of reading + 5 counts) at 501 - 1000 Hz, and output current (RMS) >0.300 A					
Power (W)	Range		A Power + C Power					
	Accuracy		Calculated Value					
Power Apparent	Range		A VA + B VA + C VA					
(VA)	Accuracy		Calculated Value					
Power Reactive (Q)	ver Reactive (Q) Range		A VAR + B VAR + C VAR					
	Accuracy		Calculated Value					
Power Factor	Range		0-1.000					
	Accuracy		Sum P / Sum VA, Calculated and displayed to three significant digits					
Measurement (Total) Linking Parallel DC		310XAC	320XAC	340XAC		360XAC		
/oltage	Range		0.0 - 420.0 V					
	Accuracy		± (1% of reading + 2 counts) >5 V		± (1% of reading + 5 counts) >5 V			
Current (RMS)	Range	2	0.05 A - 26.00 A	0.05 A - 52.00 A	0.05 A - 104.00 A		0.05 A - 156.00 A	
		3	0.05 A - 39.00 A	0.05 A - 78.00 A	0.05 A - 156.00 A		0.05 A - 234.00 A	
	Accuracy		± (1% of reading + 5 cour Current >				reading + 5 counts) x # of Linked Units, Current >3.00 A	
Power (W)	Range	2	0 W - 2600 W	0 W - 25200 W	0 W -10400 W		0 W - 15600 W	
		3	0 W - 3900 W	0 W - 7800 W	0 W - 15600 W		0 W - 23400 W	
	Accuracy			± (2% of reading + 5 counts) x # of Linked Units				

Specifications subject to change

Why We Use Counts

APT publishes some specifications using "counts" which allows us to provide a better indication of the tester's capabilities across measurement ranges. A count refers to the lowest resolution of the display for a given measurement range. For example, if the resolution for voltage is 1V then 2 counts = 2V.

KeyL = Low Limit RangeL (2) = Low Limit Range 2 Units LinkedH (2) = High Limit Range 2 Units Linked2 = 2 Units LinkedH = High Limit RangeL (3) = Low Limit Range 3 Units LinkedH (3) = High Limit Range 3 Units Linked3 = 3 Units Linked
--