AMPROBE®

Data Sheet



THWD-10 RH Meter

Perform precision temperature and humidity measurement for HVAC, Indoor Air Quality and environmental applications. The large LCD display, full suite of measuring features and two temperature probes (internal and external) make this product a preferred choice for a professional.

- Highly stable humidity measurement ±2.5%
- Processing relative humidity and temperature measurements simultaneously
- **■** Two temperature sensors (internal and external)
- Wet/dry bulb, dew point measurement
- **■** Easy selection between K/NTC/K-DP
- MAX/MIN/Average/Relative Zero and HOLD functions

No hassle warranty

No waiting.

No shipping charges.



Our commitment to high-quality products and customer service is demonstrated by our industry exclusive "No Hassle" warranty. In the unlikely event that an Amprobe Test Tool requires warranty service, any of our local dealers are authorized to replace it, on the spot.

(note: \$500 MSLP limit)









THWD-10 RH Meter Data Sheet

General Specifications

5 digit liquid crystal display (LCD).
Automatic, positive implied, negative polarity indication.
The "==" is displayed when the battery voltage drops below the operating level.
0°C to 50°C (32°F to 122°F) <80% R.H.
5 minutes
-20°C to 60°C (-4°F to 140°F) <70% R.H. with battery removed from meter
Stated accuracy at 23°C ±5°C, <75% R.H.
1.5Vx4pcs AAA size.
200 hours typical
L241.3 X W157.98 XH76.2mm (9.5 X 6.22 X3 in)
Approx. 286g (0.63 lb) including batteries.





THWD-10 RH Meter Data Sheet

Electrical Specifications

<u>=::::::::::::::::::::::::::::::::::::</u>	•••
Temperature Scale	Celsius or Fahrenheit user-selectable
Measurement Range	K-Type -50°C to 1000°C, (-50°F to 1832°F)
Resolution	0.1°C or 0.2°F
Accuracy	Accuracy is specified for operating temperatures over the range of 18° C to 28° C (64° F to 82° F), for 1 year, not including thermocouple error. $\pm(0.1\% \text{ rdg} + 1^{\circ}\text{C})$ on -50°C to $1000^{\circ}\text{C} \pm(0.1\% \text{ rdg} + 2^{\circ}\text{F})$ on -50°F to 1832° F $\pm(0.05\% \text{ rdg} + 1.4^{\circ}\text{F})$ -58°F to -328°F
Sensor	Thermistor temperature sensor
Range	0°C to 60°C, (32°F to 140°F)
Resolution	0.1°C/°F
Accuracy	$\pm 2^{\circ}$ C on 0°C to 10°C $\pm 0.5^{\circ}$ C on 10°C to 45°C $\pm 2^{\circ}$ C on 45°C to 60°C $\pm 4^{\circ}$ F on 32°F to 50°F $\pm 1^{\circ}$ F on 50°F to 113°F $\pm 4^{\circ}$ F on 113°F to 140°F
RELATIVE HUMIDITY	
Sensor	Capacitive Humidity Sensor
Range	0% to 100% RH
Accuracy	±2.5% at 25°C (77°F), 10% to 90% RH,
	±5% at 25°C (77°F), 0% to 10% RH,
	90% to 100% RH
Sensor Response Time for 90% of Total Range	60 sec typical
Sensor Hysteresis (excursion of 10% to 90% to 10% RH)	±1%RH typical
Temperature	0.1 times the applicable accuracy
Coefficient	specification per °C from 0°C to 18°C and 28°C to 50°C (32°F to 64°F and 82°F to 122°F).
Input Protection	24V dc or 24V ac rms maximum input Voltage on any combination of input pins.
Input Connector	Accepts standard miniature thermocouple connectors (flat blades spaced 7.9mm, center to center).
Included Accessories	Users manual, Battery(4), K-type thermocouple



205 Westwood Ave Long Branch, NJ 07740 1-877-742-TEST (8378) Fax: (732) 222-7088 salesteam@Tequipment.NET



THWD-10 RH Meter Data Sheet





©2010 Amprobe Test Tools. All rights reserved. 6/2010 THWD-10_DS Rev A