

# Quick Start Card

## Using the Optoma Ultra Short Throw Projector

### How to setup computer:

**Step 1:** Connect the projector and computer by VGA or HDMI or USB cable.



VGA Cable



HDMI Cable



USB Cable

**Step 2:** Power on the projector and the computer.

#### **Step 3:** USB display

When using USB display for the first time run the exe program on the virtual cdrom drive (gets loaded once usb cable is connected between the computer and projector).

#### **Step 4a:** Laptop

Use the function keys to enable external monitor/projector.

Hold down fn key and press F(x) once to turn on the external signal port of your computer.

HP = fn + F4

Dell = fn + F8

Each manufacturer uses a different function key to enable external monitor/projector. Please refer to your laptop owner's manual to find out which function key needs to be used on your laptop.

#### **Step 4b:** Desktop computer

Windows 7: Right click on your desktop and select screen resolution.

Windows XP: Right click on your desktop and select properties and then settings.

Enable monitor2 by either cloning or extending your desktop. Click Apply and then ok.


Note: For best results, set the resolution to the native resolution of the projector.

# Quick Start Card

## Using the Optoma Ultra Short Throw Projector

### How to turn on the interactive function:



**Step 1:** After successfully setting up the computer with the projector, plug the VGA and mini USB cable between the PB/Mouse Port on the projector and the computer.

 This is required for the pen to operate.




● PB/Mouse Port

**Step 2:** Press menu and go to Options/PointBlank/Interactive and select “on” .



**Step 3:** Switch the power on for the interactive pen.

For more advanced interactive functions for the pen, please see the user manual.



# Touchboards

205 Westwood Ave, Long Branch, NJ 07740  
 Phone: 866-94 BOARDS (26273) / (732)-222-1511  
 Fax: (732)-222-7088 | E-mail: sales@touchboards.com