

IAQ Meter



Delivering test and measurement advantages for HVAC/R professionals worldwide

Test the TPI advantage

APPLICATIONS

- Check ambient CO and CO2 levels in work and living spaces
- Monitor results of air control systems
- Ambient air temperature and Humidity
- Test dew point and wet bulb humidity



FEATURES & BENEFITS

- Calculate percent outside air to maintain acceptable CO2 levels in buildings and work spaces
- Measure and display Carbon Dioxide (CO2) and Carbon Monoxide
- Measure ambient air temperature
- Measure relative humidity, dew point and wet bulb
- Log up to 10,000 readings in 1 second to 1 hour intervals
- Download to a computer using the A368 USB cable



205 Westwood Ave
 Long Branch, NJ 07740
 1-877-742-TEST (8378)
 Fax: (732) 222-7088
 salesteam@Tequipment.NET

MEASUREMENTS

CO2
 Temperature
 Relative Humidity
 Dew Point
 Wet Bulb
 CO

RANGES

0 to 5000ppm
 -4 to 140°F (-20 to 60°C)
 5 to 95%
 -47 to 135°F (-44 to 57°C)
 3 to 135°F (-16 to 57°C)
 0 to 500ppm