




## VIP-100 POWER SUPPLY PREPARATION

Step 1. Cut off a 5" length from the power cable to use as a jumper.



Step 2. Strip insulation back 3/16" from the end of the cables




Powered by an ENERGY STAR® qualified adapter for a better environment

Step 3. Join the jumper to the power cable end in a parallel connection as shown



Step 4. Insert the cables as shown so that the jumper feeds power to both devices. Due to the unit's design, the polarity is not important.



Step 5. Screw down the connections and tug on them to check for loose cables.

FSR Inc.  
244 Bergen Blvd.  
West Paterson NJ 07424  
Ph 973-785-4347 Fax 973-785-4207  
[www.fsrinc.com](http://www.fsrinc.com)