Backpack Kit - Splice, Test & Prep Fiber







FiberFox and Pelican have partnered to offer the most rugged and durable backpack splicing kits in the market. These kits include all the accessories needed for techs to install, test, troubleshoot, and restore fiber networks.

Included is our <u>standard splicing kit</u> with <u>three factory calibrations</u>, the popular <u>Simple Fiber Tool Kit</u>, and <u>LC/SC cleaning pens</u>. <u>Two batteries</u>, extra cleavers, optical power meter, VFL, thermal stripper, fiber holders, cleaning and prep supplies, and hand tools plus much more is included. <u>Three-year warranty</u> on the splicer.





The Pelican backpack features a built-in <u>crushproof and watertight hard case at the back</u>
that will accommodate up to a 15" or select 17" laptops. The main compartment provides dedicated sections made of removable, padded, touch-fastened dividers. A rigid front plate provides impact protection for the main compartment and unzips all the way down on both sides for complete access to your splicing gear.

Part Number	Description
Mini6s-Backpack	Mini 6s-FT3X core alignment splicer kit, Simple Fiber Tool Kit, LC/SC Cleaning Pens, Pelican Backpack. 3 Year Warranty
Mini12r-Backpack	Mini12r-FT3X ribbon splicer kit, Simple Fiber Tool Kit, LC/SC Cleaning Pens, Pelican Backpack. 3 Year Warranty
Mini4s-Backpack	Mini4s-FT3X clad alignment splicer kit, Simple Fiber Tool Kit, LC/SC Cleaning Pens, Pelican Backpack. 3 Year Warranty

STANDARD ACCESSORIES

Splicing

Mini Series Splicer	12f Fiber Holders (12R) (FH-12)	Splice Sleeves (6S,4S) (SL60-100)	User Manual / CD (A46), (A48)	
Two Battery Packs (A40)	Power Cord (A43)	Splice Sleeves (12R) (SL40R-50)	3-Pack Calibrations (FT3X)	
Cooling Tray (A57)	AC Adapter (A51)	Spare Electrodes (A52)	Splice Tray Holder (STH)	
250um Fiber Holders (FH-250)	Car Charger (A44)	SOC HOLDER (FOX-SOCHOLDER)	SOC Heater Block (A56)	
900um Fiber Holders (FH-900)	Phillips Screwdriver (FPS1)	SOC HOLDER (FOX-SOCHOLDER2/3)	USB Firmware Update Cable (A45)	
Three Pack Calibration includes factory refresh, software updates, new electrodes, Clean Optical Components, diagnostic and performance Test (FT3X)				

Preparing

<u> </u>			
Thermal Stripper (HS-12)	Lint Free Wipes (50) (C2)	Two Hole Miller Pliers (SFT-KIT)	Sweeper Brush (12R) (FSB12)
Precision Cleaver (12r)* (Mini50GB)	Magnifier (5x) w/ LED Light (FMG5)	Lint Free Swabs (100) (12R) (C4)	Alcohol Bottle (SFT-KIT)
Basic Fiber Cleaver (SFT-KIT)	Three Hole Stripper (A61)	V-Groove Cleaning Pen (12R) (FVP12)	KS1 Shears (FKS1)
"One Tap" Cleaning Fluid (C1)	Jacket Stripper (2,3mm) (SFT-KIT)	Anti-Static Brush (12R) (FST12)	Utility knife (FK1)

^{*12}r comes with two cleavers

Testing

Optical Power meter (SFT-KIT)	1MW VFL (SFT-KIT)	Cleaning Pen 2.5mm (CP-125)			
(includes 1.25 mm adaptor)	(includes 1.25 mm adaptor)	Cleaning Pen 1.25mm (CP-250)			

