

SIMPSON ELECTRIC COMPANY

Changes to Simpson Sound Level Products

Due to the unavailability of the microphone that Simpson used on the 884-2 and 886-2 products, Simpson had to make changes to its products. We have gone from a 1" size microphone to a ¹/₂" size microphone. An adapter was used to place the smaller microphone into the same place the larger one was. This was done so that the change can be retrofitted to older units, presently in the field and in use, with minimal work.

However, with this change the 890-2 calibrator, as it is, cannot be used with the new versions of 884-2 and 886-2 units. The 890-2 unit will still be available as there are still 884's and 886's units still in the field with the 1" microphones and customers may still need replacement calibrators. New unit kits will have the 884-2 and 886-2 sold with the 887-2 calibrators. This calibrator is designed to work with the ½" size microphone, like our 897 Dosimeter unit, and will now be designated for the upgraded 884-2 and 886-2 units. If you are purchasing new sound level units and a separate calibrator in an order, not as a kit, please verify which calibrator you require. We may still inquire on your selection as a precaution and verification.

If you have questions on these changes or with what your unit requires, please contact either Technical Support or Customer Service. Both can be found on our web site, <u>www.simpsonelectric.com</u>, by clicking on the 'CONTACT US' at the top of the screen.